



QC



PAst papers

عندما تطمح في شيء وتسعى جادا في الحصول
عليه.. فإن العالم بأسره يكون في صفك
باولو كويلو

Hannah Diab
0085503

Exam duration: 3:00-5:00

Q.(1:4) Please answer the following questions concisely

(a) What is the traditional and modern definitions of quality? How can internal and external costs be disappeared?

Traditional: fitness for use

Modern: ~~inner~~ quality is inversely proportional to variability

Internal costs: ~~by~~ if there were no defects in the product.

External costs: would disappear if every unit of product conformed to requirements.

(b) Illustrate the efficiency of statistical techniques for quality improvement.



(c) What are the advantages of box plots?

It's a graphical display that simultaneously displays several important features of the data, such as location of Central Tendency, spread of variability, departure from symmetry, identification of observations that lie unusually far from the Data (outliers).

(d) What are the limitations of histogram?

- 1- sensitive to number and width of bins
- 2- ~~for large (n)~~ is best used for large data because small (n) it may change dramatically.
- 3- Doesn't take the time order of the observations into account.

Q (2:8 pt): An assembly consists of three linkage components normally distributed with means and variances as follows $X_1 \sim N(8, 0.04)$, $X_2 \sim N(5, 0.01)$, $X_3 \sim N(10, 0.09)$. Links are produced by different machines and operators. Assuming these components are produced independently. The final length y is the sum of the three dimensions. $\bar{x}_1$, $\bar{x}_2$, and $\bar{x}_3$ denote the averages of components 1, 2, and 3, respectively. Also, let $\bar{y}$ represent the average final length. Use α of 0.05. Please calculate the followings:

(a) What is the probability that the final length falls between 22 and 24?

$y = \bar{x}_1 + \bar{x}_2 + \bar{x}_3 = 8 + 5 + 10 = 23$
 $\mu_y = \mu_1 + \mu_2 + \mu_3 = 8 + 5 + 10 = 23$
 $\sigma_y^2 = \sigma_1^2 + \sigma_2^2 + \sigma_3^2 = 0.04 + 0.01 + 0.09 = 0.14$
 $\sigma_y = 0.374$
 $z = \frac{x - \mu}{\sigma}$
 $P(22 \leq y \leq 24) = P(y \leq 24) - P(y \leq 22)$
 $= P(z \leq \frac{24-23}{0.374}) - P(z \leq \frac{22-23}{0.374})$
 $= P(z \leq 2.674) - P(z \leq -2.674)$
 $= 0.996207 - 0.003793 = 0.992414$

(b) A random sample of 16 assemblies are taken, the average final length, $\bar{y}$, is found 24. Test the hypothesis that mean of the final length is less than 22.5. What is the approximate p value?

$n = 16$
 $\bar{y} = 24$
 $\alpha = 0.05$
 $H_0: \mu = 22.5$
 $H_1: \mu < 22.5$
 $1 \text{ population, } 1 \text{ side}$
 $z_0 = \frac{\bar{x} - \mu_0}{\frac{\sigma}{\sqrt{n}}} = \frac{24 - 22.5}{\frac{0.374}{\sqrt{16}}} = \frac{1.5}{0.0935} = 16$
 $\text{Since } z_0 > z_{0.05} \therefore \text{fail to reject } H_0$
 $p\text{-value is } \phi(z_0) = \phi(16) \approx 0$

(c) A random sample of 25 components are taken, the average length of component 1, $\bar{x}_1$, is found 8.6. Test the hypothesis that the mean is larger than 8.

$n = 25$
 $\bar{x}_1 = 8.6$
 $\sigma_1^2 = 0.04 \rightarrow \sigma_1 = 0.02$
 $H_0: \mu = 8$
 $H_1: \mu > 8$
 $1 \text{ population, } 1 \text{ side}$
 $z_0 = \frac{\bar{x} - \mu_0}{\frac{\sigma}{\sqrt{n}}} = \frac{8.6 - 8}{\frac{0.02}{\sqrt{25}}} = \frac{0.6}{0.004} = 150$
 $\therefore z_0 > z_{0.05} \therefore \text{reject } H_0$

(d) Construct a 95% two-sided confidence interval on the mean of the first component.

$\alpha = 0.05 \rightarrow \frac{\alpha}{2} = 0.025$
 $\bar{x}_1 - z_{\frac{\alpha}{2}} * \frac{\sigma}{\sqrt{n}} \leq \mu_1 \leq \bar{x}_1 + z_{0.025} * \frac{\sigma}{\sqrt{n}}$
 $8.6 - 1.96 * \frac{0.02}{\sqrt{25}} \leq \mu_1 \leq 8.6 + 1.96 * \frac{0.02}{\sqrt{25}}$
 $8.59 \leq \mu_1 \leq 8.60784$

(c) Random samples of 16 and 25 are taken from components 2 and 3, respectively, the averages lengths, $\bar{x}_2$ and $\bar{x}_3$, are measured 4.8 and 9.5, respectively. Can we conclude that the mean of component 3 is exactly two times the mean of component 2.

$$n_2 = 16 \quad \bar{x}_2 = 4.8 \quad s_2 = \sqrt{0.01} = 0.1$$

$$n_3 = 25 \quad \bar{x}_3 = 9.5 \quad s_3 = \sqrt{0.09} = 0.3$$

$$H_0: \mu_3 = 2\mu_2$$

$$H_1:$$

$$\bar{x}_1 - \bar{x}_2 - Z_{\frac{\alpha}{2}} \sqrt{\frac{s_1^2}{n_1} + \frac{s_2^2}{n_2}} \leq \mu_1 - \mu_2 \leq \bar{x}_1 - \bar{x}_2 + Z_{\frac{\alpha}{2}} \sqrt{\frac{s_1^2}{n_1} + \frac{s_2^2}{n_2}}$$

$$4.8 - 9.5 - 1.96 \sqrt{\frac{(0.1)^2}{16} + \frac{(0.3)^2}{25}} \leq \mu_1 - \mu_2 \leq$$

$$r = 4$$

Gamma

Q(3: 6pts) A system of four diodes connected in a standby mode is studied. The diode failure life is modeled and found exponentially distributed with parameters $(\lambda = 0.01)$. Please calculate the followings:

$$M = \frac{1}{\lambda} = \frac{1}{0.01} = 100 \text{ for 1 component.}$$

$$s^2 = \frac{1}{\lambda^2} = \frac{1}{(0.01)^2} = 10,000$$

(a) What is the probability that the system will fail before 100 hour.

$$P(X < 100) = 1 - \sum_{k=0}^{r-1} \frac{e^{-\lambda t} (\lambda t)^k}{k!}$$

$$\text{Gamma: } r = 4, a = 100, \lambda = 0.01$$

$$= 1 - \left(e^{-1} \frac{(1)^0}{0!} + e^{-1} \frac{(1)^1}{1!} + e^{-1} \frac{(1)^2}{2!} + e^{-1} \frac{(1)^3}{3!} \right)$$

(b) Calculate the system mean and standard deviation

$$M = \frac{r}{\lambda} = \frac{4}{0.01} = 400$$

$$s^2 = \frac{r}{\lambda^2} = \frac{4}{(0.01)^2} = 40,000 \therefore s = 200$$

$$1 - (0.3679 + 0.3679 + 0.18394) = 1 - (0.91974) = 0.08026$$

(c) Calculate the percentage of diodes that will fail before 100 hour.

$$P(X < 100) \text{ for all the diodes } \therefore \text{Gamma}$$

$$P(X < 100) \text{ for one diode } \rightarrow \text{exponential}$$

$$P(X < 100) = 1 - e^{-\lambda t} = 1 - e^{-0.01 \times 100} = 0.63212$$

(d) If the diode operated for 50 hours. What is the probability that the diode will survive another 100 hours.

Exponential

$$P(X > 100) = 1 - P(X \leq 100) = 1 - (1 - e^{-\lambda t}) = e^{-\lambda t} = e^{-0.01 \times 100} = 0.3679$$

(e) If the failure rate increases to 0.02. Calculate the diode mean and standard deviation.

$$\text{Exponential} \rightarrow M = \frac{1}{\lambda} = \frac{1}{0.02} = 50$$

$$s^2 = \frac{1}{\lambda^2} = \frac{1}{(0.02)^2} = 2500 \therefore s = 50$$

- (ii) Suppose that the system is changed to active parallel system in which at least three components should operate to make the system work successfully. Calculate the probability the system will operate 400 hours.

Gamma $\rightarrow P(X=400), r=4, \lambda=0.01$

$$f(400) = P(X=400) = \frac{\lambda^r}{\Gamma(r)} \cdot (\lambda x)^{r-1} \cdot e^{-\lambda x} = \frac{0.01^4}{\Gamma(4)} \cdot (0.01 \times 400)^3 \cdot e^{-(0.01 \times 400)}$$

$$= \frac{0.01^4}{6} \cdot 64 \cdot e^{-4} = 1.66 \times 10^{-3} \times 64 \times 0.01832 = 1.946 \times 10^{-3}$$

either 3 are working or all of them

Q(4:4 pt) The variabilities of the service times of two bank tellers are of main interest. A random sample of 9 observations from the 1st teller yields a sample average of 3.4 minutes with a variance of 0.16 minutes. A random sample of 16 observations from the 2nd teller yields a sample average of 2.5 minutes with a variance of 0.25 minutes. Use α of 0.01 to

2 populations $\alpha = 0.05$ $\alpha = 0.01$

(a) Test the hypothesis that the standard deviation of the service time for the first teller is identical to the standard deviation of the service time for the 2nd teller.

$$H_0: \frac{\sigma_1^2}{\sigma_2^2} = 1$$

$$H_1: \frac{\sigma_1^2}{\sigma_2^2} \neq 1$$

F-distribution

$$F_0 = \frac{s_1^2}{s_2^2} = \frac{(0.4)^2}{(0.5)^2} = 0.64$$

F_0 is between $F_{0.025, 8, 15}$ and $F_{0.975, 8, 15}$

$\therefore$ fail to reject H_0 $\therefore \frac{\sigma_1^2}{\sigma_2^2} = 1$

(b) Test the hypothesis that the service time for the first teller is greater than the service time for the 2nd teller by one. Assume equal variances.

$$H_0: \mu_1 - \mu_2 = 1$$

$$H_1: \mu_1 - \mu_2 > 1$$

t-distribution case ① for cause equal $\sigma_1 = \sigma_2$

$$s_p^2 = \frac{(n_1-1)s_1^2 + (n_2-1)s_2^2}{n_1+n_2-2}$$

$$s_p^2 = \frac{8 \times (0.4)^2 + 15 \times (0.5)^2}{8+16-2} = 0.22$$

$$s_p = 0.468$$

$$t_0 = \frac{\bar{x}_1 - \bar{x}_2 - \Delta}{s_p \sqrt{\frac{1}{n_1} + \frac{1}{n_2}}} = \frac{3.4 - 2.5 - 1}{0.468 \sqrt{\frac{1}{9} + \frac{1}{16}}} = -0.513$$

(c) Construct a 95% upper confidence interval on the mean of the 2nd teller.

1 population

$$\mu_2 \leq \bar{x}_2 + t_{\alpha, n-1} \frac{s_2}{\sqrt{n}}$$

$$\mu_2 \leq 2.5 + 1.753 \times \frac{0.5}{\sqrt{16}}$$

$$\mu_2 \leq 2.72$$

$t_0 < t_{0.05, 23}$ $\therefore$ fail to reject H_0

$$t_{0.05, 23} = 1.714$$

(d) Construct a 95% lower confidence interval on the variance of the service time of the 1st teller.

$$\frac{(n-1) \times s^2}{\chi^2_{0.05, (n-1)}} \leq \sigma^2$$

$$\chi^2_{0.05, (n-1)}$$

$$8 \times (0.4)^2 \leq \sigma^2 \rightarrow 16.92 \leq \sigma^2$$

$$\frac{1}{2} \quad 0.07565 \leq \sigma^2$$

Q(5:2 pt) Consider a lot of 100 parts, of which 10 are nonconforming. If a sample of 10 parts is selected, what is the probability of obtaining 2 nonconforming items? Use a proper approximation to calculate the required probability? Check whether the approximation is satisfactory or not?

$$N = 100$$

$$D = 10$$

$$n = 10$$

$$X = 2$$

$$\text{From Hypergeometric to Binomial } P(X) = \binom{n}{x} p^x (1-p)^{n-x}$$

$$\frac{n}{N} \leq 0.1 \rightarrow \frac{10}{100} \leq 0.1 \rightarrow 0.1 \leq 0.1 \text{ i. not satisfactory}$$

$$P = \frac{D}{N} = 0.1 \rightarrow P(X=2) = \binom{10}{2} (0.1)^2 * (1-0.1)^8$$

$$= \frac{10!}{2! * 8!} * (0.1)^2 * (1-0.1)^8 = 0.194$$

Q (6:2 pt) A company is interested in determining whether the proportions of nonconforming items are unequal for two of its vendors. A random sample of 200 items from the 1st vendor revealed 10 nonconforming items. A random sample of 300 items from the 2nd vendor showed 15 nonconforming items. Construct a 90% confidence interval on the difference between the two proportions.

$$n_1 = 200$$

$$X_1 = 10$$

$$\hat{p}_1 = \frac{X_1}{n_1} = 0.05$$

$$n_2 = 300$$

$$X_2 = 15$$

$$\hat{p}_2 = 0.05$$

$$\alpha = 0.1$$

$$\frac{\alpha}{2} = 0.05$$

$$\hat{p}_1 - \hat{p}_2 - Z_{0.05} \sqrt{\hat{p}_1(1-\hat{p}_1) + \hat{p}_2(1-\hat{p}_2)}$$

$$\leq P_1 - P_2 \leq \hat{p}_1 - \hat{p}_2 + Z_{0.05} \sqrt{\hat{p}_1(1-\hat{p}_1) + \hat{p}_2(1-\hat{p}_2)}$$

$$\hat{p} = \frac{X_1 + X_2}{n_1 + n_2} = 0.05$$

$$0.05 - 0.05 - 1.645 \sqrt{\frac{0.05(1-0.05)}{200} + \frac{0.05(1-0.05)}{300}} \leq P_1 - P_2 \leq 0.05 + 1.645 \sqrt{\frac{0.05(1-0.05)}{200} + \frac{0.05(1-0.05)}{300}}$$

$$-0.033$$

$$\leq P_1 - P_2 \leq 0.033$$

(7:2 pt) The time to failure for a cathode ray tube can be modeled using a Weibull distribution with parameters $\beta = 1$ and $\theta = 200$ hours. What is the probability of a tube fail at before 800 hours?

$$P(X < 800) = 1 - \exp\left[-\left(\frac{800}{200}\right)^\beta\right] = 1 - \exp(-4)$$

$$= 1 - 0.0183$$

$$= 0.98168$$

Q(8:2pt) A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the lower specification limit such that only 0.5% of the bulbs will not exceed the limit.

$$\mu = 5000$$

$$\sigma = 50$$

$$P(Z < \frac{LSL - \mu}{\sigma}) = 0.005$$

$$2.575$$

$$\frac{5000 - LSL}{50}$$

$$LSL = 4871.25$$

$$\frac{x - \mu}{\sigma}$$

23.5
30

3.5 Q (1: pt 4) Please fill the blank with proper terms or statements.

- Quality is inversely proportional to Variability.
- Appraisal costs are those costs associated with measuring, evaluating, or auditing products, components, and purchased material to ensure conformance to the standards that have been imposed.
- The situation in which the probability of producing a product within specification limits is 0.9973 is referred to as Three sigma quality performance.
- Testing incoming material belong to Appraisal costs.
- Quality planning and training belongs to Prevention costs.
- Warranty adjustment belongs to External failure costs.
- Internal scrap and rework belong to Internal failure costs.
- The most effective statistical technique for reducing variability is Design of Experiments.
- Assignable cause may result on Change material and/or Change Tool.
- Histogram requires large data, and ignores few bins.
- A good estimator should be Unbiased and has minimum Variance.

Q (2: 4pts): Two technicians perform the same drilling operation. A random sample of 12 from the first technician gives an average machining time of 3.5 minutes with variance 0.9 minutes. A random sample of 10 from the second technician yields an average machining time of 4 minutes with variance of 0.25 minutes. Use $\alpha = 0.05$, test the hypothesis that the operator's means are equal. Assume equal variances.

$$\begin{aligned} n_1 &= 12 \\ \bar{x}_1 &= 3.5 \\ \sigma_1^2 &= 0.9 \end{aligned}$$


$$\begin{aligned} n_2 &= 10 \\ \bar{x}_2 &= 4 \\ \sigma_2^2 &= 0.25 \\ \alpha &= 0.05 \end{aligned}$$

Variance are known

$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$Z_0 = \frac{(\bar{x}_1 - \bar{x}_2) - (\mu_1 - \mu_2)}{\sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}} = \frac{(3.5 - 4) - 0}{\sqrt{\frac{0.9}{12} + \frac{0.25}{10}}} = -1.5811$$



Fail to reject H_0

$$\therefore \mu_1 - \mu_2 = 0$$

Q (3: 6 pts): The time to process purchase orders is normally distributed. A random sample of 16 orders is selected. The average processing time is found to be 9 days with a standard deviation of 2.2. Use α of 0.05


a- Can you conclude that the standard deviation is larger than 2.

$$n = 16$$

$$\bar{x} = 9$$

$$s = 2.2$$

$$\alpha = 0.05$$



$$H_0: \sigma_1^2 = \sigma_2^2 \quad H_0: \sigma_1^2 = 4$$

$$H_1: \sigma_1^2 > 4$$

$$\chi^2 = \frac{(n-1)s^2}{\sigma^2} = \frac{15(2.2)^2}{4} = 18.15$$

fail to reject H_0

$$\therefore \sigma_1^2 = 4$$

No, can't conclude.

c- Find the upper 90 % confidence interval for the mean of the order processing times.

$$P(\bar{x} + t_{\alpha, n-1} s/\sqrt{n} \geq M) = (1-\alpha) \cdot 1$$

$$1-\alpha = 0.9$$

$$\alpha = 0.1$$

$$P(9 + t_{0.1, 15} \cdot 2.2/\sqrt{16} \geq M) = 0.9$$

$$(9 + 1.341 \cdot (2.2/\sqrt{16})) \geq M \longrightarrow (9.73755 \geq M)$$

Q (4: 6 pts) A new purification unit is installed in a chemical process. Before its installation, a random sample of size = 25 yielded the following data about the percentage of impurity average of 22 and variance of 5. After installation, a random sample of size = 16 resulted in average of 16 and variance of 4. Use $\alpha = 0.05$

(a) Test the hypothesis that the two variances are equal.

$$n_1 = 25$$

$$\bar{x}_1 = 22$$

$$\sigma_1^2 = 5$$

$$n_2 = 16$$

$$\bar{x}_2 = 16$$

$$\sigma_2^2 = 4$$

$$H_0: \sigma_1^2 = \sigma_2^2$$

$$H_1: \sigma_1^2 \neq \sigma_2^2$$

$$F_0 = \frac{s_1^2}{s_2^2} = \frac{5}{4} = 1.25$$

$$F_{1-\alpha/2, n_1-1, n_2-1} = \frac{1}{F_{\alpha/2, n_2-1, n_1-1}} = \frac{1}{2.44} = 0.4098$$

Fail to reject H_0

$$\therefore \sigma_1^2 = \sigma_2^2$$

(b) Can you conclude that the both purification devices have the same mean percentages of impurity.

$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$Z_0 = \frac{(\bar{x}_1 - \bar{x}_2) - 0}{\sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}} = \frac{(22 - 16) - 0}{\sqrt{\frac{5}{25} + \frac{4}{16}}} = 8.944$$

Reject $H_0 \longrightarrow$ Purifications don't have same mean

(c) Construct the upper 90 % confidence interval on variance of old purification unit.

$$\left(\frac{(n-1)s^2}{\chi^2_{1-\alpha, n-1}} \geq \sigma_1^2 \right) = 9$$

$$\left(\frac{(25-1) \cdot 5}{\chi^2_{0.9, 24}} \geq \sigma_1^2 \right)$$

$$\left(\frac{24 \cdot 5}{15.66} \geq \sigma_1^2 \right) \longrightarrow (7.6628 \geq \sigma_1^2)$$

Q (5: 3 pts) A valve is produced in lots of size 36. An acceptance testing procedure consists of selecting 9 components at random from the lot without replacement and testing them. If two or more nonconforming components are found, the lot is rejected. If the lot contains four nonconforming components, calculate the desired probability using binomial approximation. Is this approximation satisfactory? Why or why not?

3

$$N = 36$$

$$n = 9$$

$$D = 4$$

$$(n, p)$$

$$P = D/M = 4/36 = .11$$

reject
x > 2

$$\frac{n}{N} \leq .1$$

$$\frac{9}{36} \leq .1$$

$$\frac{9}{36} = .25$$

the approx. not satisfactory

$$P(X \geq 2) = \sum_{x=2}^n \binom{n}{x} p^x (1-p)^{n-x}$$

$$= 1 - P(X < 2)$$

$$= 1 - [P(X=0) + P(X=1)] \Rightarrow 1 - \left[\binom{9}{0} (.11)^0 (.89)^9 + \binom{9}{1} (.11)^1 (.89)^8 \right]$$

$$= 1 - [0.350356 + 0.389723] = 0.259921$$

Q (6: 7 pts): The time to failure for a cathode ray tube can be modeled using a Weibull distribution with parameters $\beta = 1$ and $\theta = 300$ hours.

4

(a) What is the probability of a tube failing before 800 hours?

because $\beta = 1 \rightarrow$ so weibull convert to exponential dis

$$\lambda = \frac{1}{\theta} = \frac{1}{300}$$

$$P(X \leq 800) = 1 - e^{-\lambda x} = 1 - e^{-\frac{1}{300} \cdot 800} = 1 - 0.6948 = 0.30517$$

(b) What is the probability that the tube will survive 300 hours?

$$P(X > 300) = e^{-\lambda x} = e^{-\frac{1}{300} \cdot 300} = 0.367879$$

(c) Suppose a system is built using three identical tubes in a standby redundant system, what is the probability that the system will survive 500 hours.

$$P(X = 500) = \sum_{k=0}^{r-1} \frac{e^{-\lambda x} (\lambda x)^k}{k!}$$

$\Rightarrow$ convert to gamma

$$r = 3$$

$$\lambda = \frac{1}{300}$$

$$= e^{-\frac{1}{300} \cdot 500} \left(\frac{\frac{1}{300} \cdot 500}{0!} + \frac{\left(\frac{1}{300} \cdot 500 \right)^1}{1!} + \frac{\left(\frac{1}{300} \cdot 500 \right)^2}{2!} \right) = 0.1887 + 0.3148 + 0.2623$$

(d) Assume the system in part c can operate with at least 2 tubes, what is the probability of system operation? (hint, use the result of part b)

$$P(r \geq 2) = 1 - P(r < 2)$$

$$= 1 - 0.76517 = 0.23483$$

r > 2

$$= 0.76517$$

QC

Q (1:10 pts) Please state whether the following is true or false (T/F), underline the false part then correct it:

1. How easy it is to repair the product? refers to durability. (X) Serviceability
2. The sensitizing rules are also called the zone rules. (X) The Western Electric rules
3. Traditional definition of quality is fitness for use. (✓) -----
4. Taste and appearance are examples of sensory critical-to-quality characteristics. (✓) -----
5. Design of experiment technique is the most efficient tools in reducing variability. (✓) -----
6. Product inspection and test is an example of appraisal costs. (✓) -----
7. Liability is an example of external failure costs. (✓) -----
8. Prevention costs are those associated with efforts in design and manufacturing that are directed toward the prevention of nonconformance. (✓) -----
9. In statistical six-sigma, the fraction nonconforming is 0.002 ppm. (X) defective ~~nonconforming~~
10. A histogram is more compact summary of data than a stem-and-leaf plot. (✓) -----
11. The box-plot is a graphical display that simultaneously several important features (location, spread, etc) of the data. (✓) -----
12. The control limit contains target and two control limits. (X) control chart - CL → (control chart) (center line CL)
13. The specification limits are used to decide about product acceptance or rejection. (✓) -----
14. There is no mathematical relationship between specification limits and control limits. (✓) -----
15. The rational subgroup concept means that the chance for differences between subgroups will be maximized, while the chance for differences within subgroup will be minimized. (✓) -----
16. Random sampling is performed by taking each sample of units of product that are representative of all units that have been produced since the last sample was taken. (✓) -----
17. A run of length eight or more points has a very low probability of occurrence in a random sample of points. (✓) -----
18. Check sheet is simply a frequency distribution of attribute data arranged by category. (X) Pareto chart
19. The defect concentration diagram is analyzed to determine whether the location of the defects on unit conveys any useful information about the potential causes of the defects. (✓) -----
20. A process operating under the existence of assignable causes is said to be out-of-control. (✓) -----

The life $\sim N(7000, (1000)^2)$


$$\mu = 7000$$

~~1/4~~

Q (4: 4 pts) The specification on an electronic component in a target-acquisition system are that life is must be between 5,000 and 10,000 hr. The life is normally distributed with mean 7000. The manufacturer realizes a price of \$10 per unit processed. However, defective units must be replaced at a cost of \$5 to the manufacturer. The standard deviation is 1000 hr.

$$\mu = 7000$$

$$n = 5000$$



- Calculate the expected profit when 5,000 are sold.

$$10 \times 5000 = \$50,000$$

$$P(X \leq 5000)$$

$$P(Z \leq -2)$$

$$50,000 - 568.75$$

$$= 49,431.25$$

the expected profit

$\frac{1}{2}$

$= 0.02275$ the prop to be defective.

$$\Rightarrow 5000 \times 0.02275 = 113.75 \Rightarrow \text{may be } \text{defective}$$

$$\text{so } 5 \times 113.75 = 568.75$$

- If a sample of 40 units are selected with the same mean and standard deviation. What is the probability that mean life will exceed 10,000?

$$n = 40 \quad \mu \text{ \& } \sigma \text{ are the same.}$$

$$P(X > 10000) = 1 - P(X \leq 10000) = 1 - P(Z \leq \frac{10000 - 7000}{1000})$$

$$= 1 - P(Z \leq 3) = 1 - 0.998650 = 0.00135$$

Q (5: 5 pts) A system is composed of 4 electronic units that are exponentially distributed with mean life to failure of 500 hours.

$$r = 4$$

$$\mu = \frac{1}{\lambda} = 500$$

$$\lambda = \frac{1}{500} = 0.002$$

- What is the probability the unit will fail before its 500 hours. use expo. dist.


$$F(a) = F(500) = 1 - e^{-\lambda(500)}$$

$$= 1 - e^{-0.002(500)} = 0.63212$$



- What is the probability that the unit will operate 400 if it operated 300 hours.

$$F(a) = F(400) = 1 - e^{-0.002(400)} = 0.5507$$



- What is the probability that the system will survive 500 hours if the units are arranged in a stand-by configuration? use Gamma dist.

$$r = 4$$

$$\lambda = 0.002$$

$$R(500) = \sum_{k=0}^{4-1} \frac{e^{-\lambda(500)} [\lambda(500)]^k}{k!}$$

$$= \frac{e^{-1} (1)^0}{0!} + \frac{e^{-1} (1)^1}{1!} + \frac{e^{-1} (1)^2}{2!} + \frac{e^{-1} (1)^3}{3!} = 0.3679 + 0.18395 + 0.122$$


28.5

Section: 9-10 232

4.5

1. The control chart detects assignable and chance causes. (----- False / (only assignable) -----)
2. A product is considered defective if it contains one or more minor nonconformities. (----- True -----)
3. Quality is directly proportional to variability. (----- False / (inversely) -----)
4. When six-sigma is used, the fraction nonconforming is 3.4 ppm. (----- True -----)
5. Length and hardness are examples of sensory quality characteristics. (----- False / (physical) -----)
6. Internal failure happens when a product fails to operate successfully. (----- False / (External) -----)
7. Inspection and test of incoming material is an example of prevention costs. (----- False / (Appraisal) -----)
8. SPC reduces variability more than design of experiment. (----- True -----)
9. SPC is based on sound underlying principles and can only be applied to industrial processes. (----- True -----)
10. Fitness for use is the modern definition of quality. (----- False / (traditional) -----)
11. Specification limits are the parameters of the control chart. (----- True -----)
12. Aesthetics is "What is the reputation of the company or its products?" (----- True -----)
13. The Histogram is simply a frequency distribution of attribute data arranged by category. (----- True -----)
14. The defect concentration is a formal tool frequently useful in underlying potential causes. (----- True -----)
15. The scatter diagram is a useful plot for identifying a potential relationship between two variables. (----- True -----)
16. A process operating in the existence of assignable causes is said to be in-control. (----- False / (out of control) -----)
17. Control charts are used to improve the process and estimating specification limits. (----- True -----)
18. When a process is operating properly, an out-of-control action plan should be done. (----- True -----)
19. SPC is effective in eliminating variability. (----- True -----)
20. Stem and leaf displays the three quartiles, the minimum, and the maximum of the data on a rectangular box. (----- False / (box plot) -----)

9



Q (3): Three identical components are arranged in a standby redundant system. If the useful life of each component is described by an exponential distribution with mean failure rate of 300 hr. Please answer the followings: (10 pts)

$$\frac{1}{\lambda} = 300$$

a- Write down the density function for the useful life of the system. (2 pts)

$$\Rightarrow \lambda = 0.003$$

exponential $f(x) = \lambda e^{-\lambda x}$


b- What is the probability that a component will fail before 250 hr? (2 pts)

$$P(X \leq a) = 1 - e^{-\lambda a} = 1 - e^{-0.003 \times 250} = 1 - 0.472 = 0.528$$

c- What is the probability that the system will survive more than 600 hrs? (3 pts)

$P \text{ to survive} = 1 - P \text{ to failure}$
 $P(X \leq 600) = 1 - e^{-0.003 \times 600} = 1 - 0.165 = 0.835$
 $\Rightarrow \text{prob. to survive} = 0.165$

d- If the useful life of the system is approximately described by a normal distribution, what is the probability that the system will survive more than 600 hrs? (3 pts)



$$P(X > 600) = 1 - P(X \leq 600)$$

Standardization $\Rightarrow$

$$1 - \Phi\left(\frac{600 - 300}{\sigma}\right) = 1 - \Phi(0.9) = 1 - 0.815 = 0.18406$$

Probability of survive = 0.18406

Q (4): A system consists of three modules A, B and C connected in-series. The time to failure of module A follows a Weibull distribution with scale parameter $\theta = 100$ hours and $\beta = 3.2$. The time to failure of module B follows the normal distribution with mean $\mu = 400$ cycles and standard deviation $\sigma = 32$ cycles. It was also noted that during 1 hour, module B performs 12 cycles. Find the probability that the system will survive up to 240 cycles of module B. (4 pts)

per unit



Weibull	Normal
$\theta = 100$	$\mu = 400$
$\beta = 3.2$	$\sigma = 32$

Q(5) The filling of glass bottles with a soft-drink beverage can be performed on two machines. The filling processes have known standard deviations of 0.03 and 0.02 liters, respectively. A random sample of 25 bottles is taken from the production of the first machine, where as a sample of 20 bottles is selected from the second machine. The averages of net weight are 2.6 and 2.8 liters, respectively. Please answer the followings: (5pts)

a- What are the quality characteristic and its type?

filling of glass (weight) $\Rightarrow$ physical quality characteristic

b- Test the hypothesis that both machines fill the same net contents, using $\alpha = 0.05$.

2 populations $\Rightarrow$ test of mean difference & variances known


$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$Z_0 = \frac{\bar{X}_1 - \bar{X}_2 - \Delta_0}{\sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}}$$

$$\Rightarrow Z_0 = \frac{2.6 - 2.8}{\sqrt{\frac{0.03^2}{25} + \frac{0.02^2}{20}}}$$

$$\Rightarrow Z_0 = \frac{-0.2}{\sqrt{0.00036 + 0.0002}} = \frac{-0.2}{\sqrt{0.00056}} = \frac{-0.2}{0.02366} = -8.45$$



reject H_0

$\Rightarrow$ reject H_0
 $\Rightarrow$ All same net contents

c- Calculate the P-value for the test.

$$P\text{-value} = 2[1 - \Phi(|Z_0|)]$$

Q (6): Two operators perform the same machining operation. Their supervisor wants to estimate the difference in the mean machining times between them. A random sample of 10 from the first operator gives an average machining time of 4.6 minutes with a standard deviation of 0.4 minutes. A random sample of 8 from the second operator yields an average machining time of 5.4 minutes with a standard deviation of 0.5 minutes. Use $\alpha=0.05$. (10 pts)

a- Test the hypothesis that the two variances are equal. (4pts)

$$n_1 = 10, \bar{X}_1 = 4.6, S_1^2 = 0.4$$


$$n_2 = 8, \bar{X}_2 = 5.4, S_2^2 = 0.5$$

$$H_0: \sigma_1^2 = \sigma_2^2$$

$$H_1: \sigma_1^2 \neq \sigma_2^2$$

$$F_0 = \frac{S_1^2}{S_2^2}$$

$$\Rightarrow \frac{0.4^2}{0.5^2} = \frac{0.16}{0.25} = 0.64$$



$$F_{0.025, 9, 7} = 4.82$$

$$F_{0.975, 9, 7} = 0.21$$

fail to reject H_0

b- If the mean machining time of the second operator should be exceed the mean of the first operator by 0.6. Can we support this hypothesis? (4 pts)

$$\mu_2 - \mu_1 = 0.6$$

$$\sigma_1^2 \neq \sigma_2^2$$

c- Find a 95% lower confidence interval for the mean machining times of the second operator. (2pts)

Q (7): The variability of the time to be admitted in a health care facility is of concern. A random sample of 15 patients shows a mean time to admission of 2.2 hours with a standard deviation of 0.2 hours. (5 pts)

a- Can we conclude that the variance of time to admission is less than 0.06 at α of 0.01? (3pts)

$n=15$ $\bar{x}=2.2$ $s=0.2$

$H_0: \sigma^2 = 0.06$

$\sigma^2 < 0.06 \Rightarrow \chi^2$


$\alpha=0.01$

$\chi^2_0 = \frac{(n-1) \cdot s^2}{\sigma_0^2} = \frac{14 \cdot 0.2^2}{0.06} = 155.55$

$\chi^2_{1-\alpha, n-1} = 4.66$

$\chi^2_{\alpha, n-1} = 29.14$

$\chi^2_0 = 155.55$



$\Rightarrow$ No we can't conclude

b- Find a 95% lower confidence interval for the mean machining times of the second operator. (2pts)

$\alpha=0.05$

$\bar{x} - t_{\alpha, n-1} \frac{s}{\sqrt{n}} \leq \mu$

$\Rightarrow \mu \geq 2.2 - 1.761 \cdot \frac{0.2}{\sqrt{15}}$

$\mu \geq 2.1$

Q (8): Two operators perform the same machining of applying a plastic coating to Plexiglas. We want to estimate the difference in the proportion of nonconforming parts produced by the two operators. A random sample of 100 parts from the first operation shows that there are 6 nonconforming. A random sample of 200 parts from the second operator shows that 8 are nonconforming. Use $\alpha=0.01$ (5 pts)

$n_1=100 \rightarrow 6 \text{ non}$

$n_2=200 \rightarrow 8 \text{ non}$

a- Can we conclude that the difference in the proportion of nonconforming parts produced by the two operators is greater than 0.018? (3pts)

2-POP

$\hat{p} = \frac{x}{n} \Rightarrow \hat{p}_1 = \frac{6}{100} = 0.06$


$\hat{p}_2 = \frac{8}{200} = 0.04$

$H_0: \hat{p}_1 - \hat{p}_2 = 0.018$

$H_a: \hat{p}_1 - \hat{p}_2 > 0.018$

$z_0 = \frac{\hat{p}_1 - \hat{p}_2 - 0.018}{\sqrt{\hat{p}(1-\hat{p})(\frac{1}{n_1} + \frac{1}{n_2})}} = 0.018$

$\sqrt{0.018 \cdot 0.982 (\frac{1}{100} + \frac{1}{200})} = 0.0162$



$\Rightarrow$ reject H_0

one sided

$z_0 = 1.11$

b- Test the hypothesis whether the proportion of nonconforming for second operator is equal to 4.5%.

$\hat{p}_2 = 0.045$

$\hat{p}_2 \neq 0.045$

$z_0 = \frac{(x + 0.5) - np_0}{\sqrt{np_0(1-p_0)}} = \frac{(8 + 0.5) - 9}{\sqrt{9 \cdot 0.045(1-0.045)}}$

$= \frac{-0.5}{2.93} = -0.17$



2-sided

$z_{\alpha/2}$

c- Calculate the P-value for the test in part (b).

$P\text{-value} = 2[1 - \phi(|z_0|)]$

Q (9) Consider a lot of 100 parts, of which 3 are nonconforming. A sample of 4 parts is selected, if approximation is used, what is the required probability of obtaining at most one nonconforming item? Is this approximation satisfactory? (3pts)

$N=100 \rightarrow 3 \text{ non}$

$n=4$ (hyper geometric $\rightarrow$ bin)

$P(X \leq 1) = P(X=0) + P(X=1)$

condition $\frac{n}{N} \leq 0.1 \Rightarrow 0.04 \leq 0.1$ satisf

$= \binom{4}{0} (0.03)^0 (1-0.03)^4 + \binom{4}{1} (0.03)^1 (1-0.03)^3$

$= 0.88 + 0.1$

$= 0.99$

$B(n, p) = B(4, 0.03)$

$P(x) = \binom{n}{x} p^x (1-p)^{n-x}$

4

3

9

University of Jordan
Dept. of Industrial Engineering
Quality Control Quiz-28-12-2011)
Instructor: Dr. Abbas Al-Refaie

Name: ~~_____~~

Reg. No. ~~_____~~

Section: 11-12:30

Q.(1:10 pts) Given the following (assume normally distributed quality characteristic):

(i) The $\bar{x}$ - R charts:

- The $\bar{x}$ chart: CL = 625 UCL = 640 LCL = 610 $n = 9$
 - The R chart: CL = 8 UCL = 16 LCL = 0
- The specifications on the product were 620 ± 8 ,

(a) Estimate the mean and standard deviation. If the sample size is changed to three, construct the R- chart.

Mean = $\bar{\bar{x}} = CL = 625$

Standard deviation = $\bar{R}/d_2$, $\bar{R} = CL = 8$ $d_{2, n=9} = 2.970$
 $= 2.6936$

$n_{old} = 9$

$UCL = D_4 \left[\frac{d_{2, new}}{d_{2, old}} \right] \bar{R}_{old} = 2.574 \left[\frac{1.693}{2.97} \right] * 8 = 11.738$

$n_{new} = 3$

$CL = \left[\frac{d_{2, new}}{d_{2, old}} \right] \bar{R}_{old} = \left[\frac{1.693}{2.97} \right] * 8 = 4.5603$

b) Calculate the process capability index. $LCL: \left[\max \{ 0, D_3 \left(\frac{d_{2, new}}{d_{2, old}} \right) \bar{R}_{old} \right] = \text{Zero} \left[\frac{1.693}{2.97} \right] * 8 = \text{Zero}$

Process Capability = $\frac{USL - LSL}{6\sigma}$

$USL = 628, LSL = 612$

$= \frac{628 - 612}{6 * 2.6936} = 0.99$

$\sigma = \bar{R}/d_2 = 8/2.97 = 2.6936$

(c) What is the probability of detecting a shift in the process mean to 640 by the third subsequent sample following the shift?

Probability of detecting = $\beta^i (1 - \beta)$
 $= 1^i (1 - 1)$
 $= \text{Zero}$

shift to 640
& Mean = 640

$\beta = 1$

University of Jordan
Dept. of Industrial Engineering
Quality Control (Mid-Exam-26-7-09)
Instructor: Dr. Abbas Al-Refaie

PLEASE PROVIDE FINAL ANSWERS WITH DETAILED CALCULATIONS AND EQUATIONS

Q.(1:23) Please fill the blank with proper terms or statements.

- 23. • Variability is inversely proportional to (1-).
- (2-) increase the sensitivity of the control charts and result in false alarm of out-of-control.
- The situation in which the probability of producing a product within specification limits is 0.9973 is referred to as (3-).
- (4-) are those costs associated with measuring, evaluating, or auditing products, components, and purchased material to ensure conformance to the standards that have been imposed.
- (5-) is a more compact summary of data than a (6-).
- The (7-) is a graphical display that simultaneously displays several important features, such as location or central tendency, spread or variability.
- (8-) is a graphical method for determining whether sample data conform to a hypothesized distribution based on a subjective visual examination of the data.
- The (9-) is the smallest level of significance that would lead to rejection of the null hypothesis.
- (10-) is a powerful collection of problem-solving tools useful in achieving process stability and improving capability through the reduction of variability.
- The process that is operating in the presence of assignable causes is said to be (11-).
- (12-) is a flow chart or text based description of the sequence of activities that must take place following the occurrence of an activating event.
- Control charts are used to (13-) and (14-).
- (15-) and (16-) are the most important properties of a good estimator.
- (17-) and (18-) are called producer's risk and consumer's risk, respectively.

Q (2:12): Two operators perform the same machining operation. Their supervisor wants to estimate the difference in the mean machining times between them. It can be assumed, however, that the distribution of machining times is normal for each operator. A random sample of 10 from the first operator gives an average machining time of 4 minutes with a standard deviation of 0.5 minutes. A random sample of 6 from the second operator yields an average machining time of 5 minutes with a standard deviation of 0.8 minutes. Use $\alpha=0.05$,

- a- Test the hypothesis that the two variances are equal. (4)
- b- Find a 95% confidence interval for the difference in the mean machining times between the two operators. (3)
- c- Test the hypothesis that the second operator's mean is larger than the first operator's mean by five. (4)
- d- How much is the approximate p value? (1)

$$\mu_2 - \mu_1 = 5$$

Kaizen Team

Q (3:8) A company is interested in determining whether the proportions of nonconforming items are unequal for two of its vendors. A random sample of 100 items from the first vendor revealed 4 nonconforming items. A random sample of 200 items from the second vendor showed 10 nonconforming items. Use α of 0.05, what can you conclude? Construct a 90 % confidence interval on the difference between the two proportions.

Q (4:12): The time to process customer orders is known to be normally distributed. A random sample of 20 orders is selected. The average processing time is found to be 8 days with a standard deviation of 1.5. Use α of 0.1

- Test the hypothesis that the standard deviation equals 2 versus the alternative hypothesis that the standard deviation is less than 2. (3)
- Use the p -value to decide whether to reject or fail to reject the null hypothesis in part (a). (4)
- Find a 90 % confidence interval for the variance of the order processing times. (1)

Q(5:9) Consider the Shewhart $\bar{x}$ -control chart with 2-sigma limits. Assume the process in control,

- Calculate the average run length (ARL) (3)
- Is ARL an effective tool for sampling? Why or why not? (show calculations) (3)
- If sampling is made every half an hour, calculate average time to signal (3)

Q(6:6) A quality characteristic of a product is normally distributed with mean 6 and standard deviation one. Specifications on the characteristic are $3 < x < 7$. A unit that falls within specifications on this quality characteristic results in a profit \$20. If $x < 3$, the profit is \$-2, whereas if $x > 7$, the profit is \$-4. Calculate the expected profit.

Q(7:6) Ferric chloride is used as a flux in some types of extraction metallurgy processes. Suppose that from long experience a reliable value for the standard deviation of flux container weight is determined to be 4 lb. How large a sample would be required to construct a 90 % two sided confidence interval on the mean that has a total width of 1 lb?

Q (8:6) It is estimated that the average number of surface defects in 20 m^2 of paper produced by a process is 4. What is the probability of finding no more than two defects in 40 m^2 of paper through random selection?


Q (9:6): The time to failure for a cathode ray tube can be modeled using a Weibull distribution with parameters $\beta = \frac{1}{3}$ and $\theta = 200$ hours. What is the probability of a tube operating for at most 800 hours?

Q(10:6) A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the lower specification limit such that only 0.5 % of the bulbs will not exceed the limit.

Q(11:6) Nonconformities occur in glass bottles according to a Poisson distribution. An inspector counts the surface-finish defects in dishwashers. A random sample of five dishwashers contain three such defects. Is there reason to conclude that the mean occurrence rate of surface-finish defects per dishwashers exceeds 0.5? Use $\alpha = 0.05$. Use the normal approximation to the poisson.

اسم الطالب	رقم الجامعي	الكلية	الدرجة	الدرجة
المستوى	الكلية	الدرجة	الدرجة	الدرجة
القسم	الدرجة	الدرجة	الدرجة	الدرجة
التاريخ	الدرجة	الدرجة	الدرجة	الدرجة

ϕ_1 23
 ϕ_{2-4} 31
 ϕ_{5-11} 42
 العلامة 97



- Q1: (1) Quality:
 (2) Warning limit
 (3) 3.2
 (4) Appraisal costs.
 (5) Histogram / (6) stream/one leaf.
 (7) Box Plot.
 (8) Probability plotting.
 (9) P-value.
 (10) Statistical process Control.
 (11) out of control process.
 (12) Out-of-Control Action Plan
 (13) improve the Process.
 (14) use as estimating device and to determine capability of the process
 (15) point estimators should be unbiased, expected value of point estimator should be parameter being estimated
 (16) point estimator should have minimum variance.
 Any point estimator is a random variable. minimum variance point estimator should have variance smaller than any other one

Kaizen Team

Q2;

$$n_1 = 10 \quad \bar{x}_1 = 4^1, \quad s_1 = 0.5$$


$$n_2 = 6 \quad \bar{x}_2 = 5, \quad s_2 = 0.8, \quad d = 0.05$$

a) $H_0: \sigma_1^2 = \sigma_2^2$

$H_1: \sigma_1^2 \neq \sigma_2^2$

$$f_0 = \frac{s_1^2}{s_2^2} = \frac{(0.5)^2}{(0.8)^2} = 0.391$$

$$F_{0.025, 9, 5} = 6.68$$



$$F_{1-\frac{\alpha}{2}, m-1, n-1} = 0.223, \quad F_{\frac{\alpha}{2}, m-1, n-1} = 6.68$$

4

$$F_{0.025, 5, 9} = 4.48$$

$\Rightarrow$ Fail to reject $H_0 \Rightarrow \sigma_1^2 = \sigma_2^2$

b) $\alpha = 0.05$

Unknown σ^2 but equal.

$$S_p^2 = \frac{9(0.5)^2 + (5)(0.8)^2}{14} = 0.3893$$

$$S_p = 0.6239$$

$$\bar{x}_1 - \bar{x}_2 - t_{\alpha/2, 14} (S_p) \sqrt{\frac{1}{n_1} + \frac{1}{n_2}} \leq \mu_1 - \mu_2 \leq \bar{x}_1 - \bar{x}_2 + t_{\alpha/2, 14} (S_p) \sqrt{\frac{1}{n_1} + \frac{1}{n_2}}$$

$$4 - 5 - 2.145(0.6239) \sqrt{\frac{1}{10} + \frac{1}{6}} \leq \mu_1 - \mu_2 \leq 4 - 5 + 2.145(0.6239) \sqrt{\frac{1}{10} + \frac{1}{6}}$$

Kaizen Team

Q2

b)

$$1.6911 < M_1 - M_2 < -0.3089$$

3

c)

$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 < 5 \quad (\mu_2 + 5 > \mu_1)$$

$$t_0 = \bar{x}_1 - \bar{x}_2 - \Delta_0$$

$$s_p \sqrt{\frac{1}{n_1} + \frac{1}{n_2}}$$


$$t_0 = 4 - 5 = -6.011$$

$$(0.6239) \sqrt{\frac{1}{10} + \frac{1}{6}}$$

$$t_{0.05, 14} = 1.761$$

$$t_{0.05, 14} = 2.145$$


N



→ reject H_0 → the 2nd mean is larger than the 1st one by five.

d) ~~Not available in tables~~

1



reject H_0

KAizen Team

Q3 $n_1 = 100$ $x_1 = 4$
 $n_2 = 200$ $x_2 = 10$ $\alpha = 0.05$

$\hat{p}_1 = \frac{x_1}{n_1} = \frac{4}{100} = 0.04$

$\hat{p}_2 = \frac{x_2}{n_2} = \frac{10}{200} = 0.05$ $H_0: p_1 = p_2$
 $H_1: p_1 \neq p_2$

$Z_0 = \hat{p}_1 - \hat{p}_2$


$$\frac{\hat{p}_1 - \hat{p}_2}{\sqrt{\hat{p}(1-\hat{p})\left(\frac{1}{n_1} + \frac{1}{n_2}\right)}}$$

$$\hat{p} = \frac{x_1 + x_2}{n_1 + n_2} = \frac{4 + 10}{100 + 200} = 0.0467$$

$$\frac{0.04 - 0.05}{\sqrt{0.0467(0.9533)\left(\frac{1}{100} + \frac{1}{200}\right)}}$$

$$= 0.0006678$$

$Z_{0.025} = 1.96$



$\Rightarrow$ Fail to reject H_0
 (they are equal)

$\alpha = 0.1$

$$\hat{p}_1 - \hat{p}_2 - Z_{\alpha/2} \sqrt{\hat{p}_1(1-\hat{p}_1) + \hat{p}_2(1-\hat{p}_2)} \leq p_1 - p_2 \leq \hat{p}_1 - \hat{p}_2 + Z_{\alpha/2} \sqrt{\hat{p}_1(1-\hat{p}_1) + \hat{p}_2(1-\hat{p}_2)}$$

$$0.04 - 0.05 - 1.64 \sqrt{0.000384 + 2.37 \times 10^{-4}} \leq p_1 - p_2 \leq 0.04 - 0.05 + 1.64 \sqrt{6.215 \times 10^{-4}}$$

$$-0.011 \leq p_1 - p_2 \leq 0.031$$

Kaizen Team..


Q. 4: $n = 20$, $\bar{x} = 8$, $s = 1.5$, $\alpha = 0.05$

a) $H_0: \sigma^2 = 4$

$H_1: \sigma^2 < 4$ (one-sided)

~~Handwritten scribbles~~


$\chi^2 = \frac{19(1.5)^2}{4} = 10.688$



$\chi_{0.95, 19} = 10.12$ (4)

→ fail to reject H_0

b) $\chi^2 = 10.688$



$P\text{-value} \approx 0.82$

(4)

→ $\alpha < P\text{-value}$ → fail to reject H_0

c) $\alpha = 0.1$

$\frac{(n-1)s^2}{\chi^2_{1-\alpha/2, n-1}} < \sigma^2 < \frac{(n-1)s^2}{\chi^2_{\alpha/2, n-1}}$

$\frac{19(1.5^2)}{\chi^2_{0.95, 19}} < \sigma^2 < \frac{19(1.5^2)}{\chi^2_{0.05, 19}}$

30.14

10.12

Kaizen Team

Q4

c) $0.1018 \leq \sigma^2 \leq 4.224$

Q5:

a) $ARL = \frac{1}{p} = \frac{1}{0.00455} = 219.78$

b) No it is not effective, ~~because~~ the standard deviation usually is approximately equal to the mean

c) $ATS = ARL \cdot h$

~~ATS~~ $ATS = 219.78 \cdot \left(\frac{1}{2}\right) = 109.89 \text{ hours}$

Q6: $\mu = 6, \sigma = 1$

$\mu = 6, \sigma = 1$

$P(3 \leq X \leq 7)$

$\mu = 6, \sigma = 1$

$= P(X \leq 7) - P(X \leq 3)$

$= P\left(\frac{7-6}{1} \leq \frac{X-\mu}{\sigma}\right) - P\left(\frac{3-6}{1} \leq \frac{X-\mu}{\sigma}\right)$

$\mu = 6, \sigma = 1$

$= P(Z \leq 1) - P(Z \leq -3)$

$= 0.84134 - 0.0044$

$= 0.83694$

اسم الطالب ~~محمد~~
 المستوى
 القسم
 التاريخ

رقم الجامعي 0076 475
 الكلية
 المادة

العلامات

Q.7.

$$\sigma = 4, n = ?, \alpha = 0.1$$


$$Z_{\alpha/2} \cdot \frac{\sigma}{\sqrt{n}} = \frac{1}{2}$$

$$\left(Z_{0.05} \cdot \frac{4}{\sqrt{n}} \right) = \frac{1}{2}$$

$$1.64 \cdot \frac{4}{\sqrt{n}} = \frac{1}{2}$$

$$6.56 = \frac{\sqrt{n}}{2} \Rightarrow \sqrt{n} = 13.12$$

$$\Rightarrow n = 172.13$$



KAIZEN Team

Q.8 : $\frac{4 \text{ defect}}{20 \text{ m}^2}$ } $\lambda = \frac{4 \times 40}{20} = 8 \text{ defects}$

$$P(X \leq 2) = P(X=2) + P(X=1) + P(X=0)$$

$$= \frac{e^{-8} (8)^2}{2!} + \frac{e^{-8} 8}{1!} + \frac{e^{-8} (8)^0}{0!}$$

$$= 0.011 + 0.00268 + 3.35 \times 10^{-4}$$

$$= 0.014$$

Q.9 : $\beta = \frac{1}{3}, \theta = 200$

$$P(X \leq 800) = 1 - \exp \left[- \left(\frac{800}{\theta_{200}} \right)^\beta \right]$$

$$= 1 - \exp \left[- (4)^{1/3} \right]$$

$$= 0.7955$$

Q.10 : $\mu = 5000, \sigma = 50$

$$P(X \leq LSL) = 0.005$$

$$P\left(Z \leq \frac{LSL - \mu}{\sigma}\right) = 0.005$$

$$P\left(Z \leq \frac{LSL - 5000}{50}\right) = 0.005$$

$$P(Z \leq 2.57) \Rightarrow \frac{LSL - 5000}{50} = 2.57$$

$$LSL = 528.5$$

KAIZEN Team ←

Q 11. $p = 5$, $D = 3$,

~~2~~
~~5~~

~~2~~

$$\frac{1}{2} \mu_x = 1 = 0.5$$

$$\sigma_x^2 = \frac{1}{n} = \frac{0.5}{5} = 0.1$$

1

KAIZEN TEAM

Kaizen Team

University of Jordan

Department of Industrial Engineering

QUALITY CONTROL (12/7/09)

DR. Al-Refai, A.

Student name: Alaa Kheilil
0076922

SR#: 20

Q(1.3) Please answer the following questions concisely:

What is the traditional definition of quality? Provide an example for each type of critical-to-quality characteristics.

Quality means fitness for use.

1) physical: weight

2) sensory: taste


3) time orientation: reliability.

What is the difference between nonconforming product and defective product?


nonconforming: that fail to meet one or more of its specifications, it is not necessarily unfit for use.

defective product: if it has one or more defect which are ~~nonconformities~~ nonconformities that are serious enough to significantly affect the safe of use (contain one or more serious nonconformities).

Draw the phase diagram for the use of quality-engineering methods:



Q2(4). Illustrate how the control charts works. Illustrate the relationship between control limits, specification limits, and natural tolerance limits.



Q3(6). Samples of fabric from a textile mill, each of 100 m^2 , are selected, and the number of occurrences of foreign matter are recorded. Data for 25 samples shows a total number of nonconformities of 180.

a:2 What is the proper control chart to be used for monitoring future production? Calculate the 3 sigma control limits for this chart.

$$\bar{c} = \frac{180}{25} = 7.2$$

$$UCL = \bar{c} + 3\sqrt{\bar{c}} = 15.25$$

$$CL = \bar{c} = 7.2$$

$$LCL = \bar{c} - 3\sqrt{\bar{c}} = 0$$

Processes with constant sample size.

b:2 Suppose a sample of 16 nonconformities is found out of control with assignable cause? What will be the effect on the control chart in part a?

$$\bar{c} = \frac{180 - 16}{24} = 6.83$$

$$UCL = 14.673$$

$$LCL = 0$$

c:2 Suppose the nonconformities are observed in 50 m^2 , calculate 2 sigma control limits for the revised limits and centerline for the revised control chart.

$$n = 1/2$$

$$n\bar{c} = 1/2 \cdot (7.2) = 3.6$$

$$n\bar{c} + 2\sqrt{n\bar{c}} = 7.4$$

$$n\bar{c} - 2\sqrt{n\bar{c}} = 0$$

Total nonconformities = 180

$$n = 100$$

$$m = 25$$

$$\bar{c} = \frac{180}{25} = 7.2$$

$$15.2$$

$$\frac{180 - 16}{24} = 6.83$$

n.c

type I error

$$\text{Detect} = 1 - \beta$$

$$\text{not Detect} = \beta$$

P in 1st or 2nd

$$P(1 - \beta) + P(\beta(1 - \beta))$$

$$P(1 - \beta) + P(\beta(1 - \beta))$$

b(4) What is the probability of detecting a shift in the process mean to 610 at the first or second subsequent sample following the shift? Assume σ remains constant $\frac{\sigma}{\delta} = 4$

$$\mu = 610$$

$$\beta = \frac{CL - \mu_{new}}{\sigma/\sqrt{n}}$$

$$(1 - \beta) = P(\bar{x} < LCL) + P(\bar{x} > UCL)$$

$$= \Phi\left(\frac{LCL - \mu_{new}}{\sigma/\sqrt{n}}\right) + 1 - \Phi\left(\frac{UCL - \mu_{new}}{\sigma/\sqrt{n}}\right)$$

$$= \Phi\left(\frac{640 - 610}{4/\sqrt{4}}\right) + 1 - \Phi\left(\frac{610 - 610}{4/\sqrt{4}}\right)$$

$$\beta = 0.0222$$

$$\beta = (1 - \text{Prob. det}) \Rightarrow \text{Prob. det} + (1 - \text{Prob. det}) \cdot (\text{Prob. det})$$

$$P(1 - \beta) + P(\beta(1 - \beta))$$

2- For $\bar{x}$ -s charts (8): (5:52)

$$0.9775 + (0.0222)(0.9775) = 0.9995$$

a(3) For $\bar{x}$ chart, find the probability of type I error, assuming σ is constant.

$$\alpha = P(\bar{x} < LCL) + P(\bar{x} > UCL)$$

$$\sigma_x = \bar{s}/c_4 = 8/0.9213 = 8.68$$

$$= \Phi\left(\frac{LCL - \bar{x}}{\sigma/\sqrt{n}}\right) + 1 - \Phi\left(\frac{UCL - \bar{x}}{\sigma/\sqrt{n}}\right)$$

$$= \Phi\left(\frac{690 - 700}{\sigma/\sqrt{n}}\right) + 1 - \Phi\left(\frac{710 - 700}{\sigma/\sqrt{n}}\right)$$

and

type 2

type 1

$$= \Phi(-2.3) + 1 - \Phi(2.3) = 2(1 - 0.98941)$$

b(5) Suppose the process mean shifts to 693 and the standard deviation shifts to 12. Find the average run length and average time to signal if samples are taken at equally spaced intervals of 0.5 hour. h

$$\mu = 693$$

$$\sigma = 12 = 0.0214$$

$$\alpha = P(\bar{x} < LCL) + P(\bar{x} > UCL)$$

$$= \Phi\left(\frac{LCL - \mu}{\sigma/\sqrt{n}}\right) + 1 - \Phi\left(\frac{UCL - \mu}{\sigma/\sqrt{n}}\right)$$

$$= \Phi(-0.5) + 1 - \Phi(2.83) = 0.3085 + 1 - 0.9977$$

$$= 0.3108$$

$$ARL = \frac{1}{\alpha} = \frac{1}{0.3108}$$

$$= 3.21$$

4/4

$$ATS = 3.21 \times 0.5 = 1.605 \text{ hr}$$

chap

m = 16
n = 4

U-chart

Q6. (6) An automobile manufacturer wishes to control the number of nonconformities in a subassembly area producing manual transmissions. The inspection unit is defined as four transmissions. The following 16 samples are collected (each of size 4).

U-chart

#	No. of nonconformities	#	No. of nonconformities
1	1	9	2
2	3	10	1
3	2	11	0
4	1	12	2
5	0	13	1
6	2	14	1
7	1	15	2
8	5	16	3

$\bar{u} = \frac{\sum c_i}{m} = \frac{27}{16} = 1.6875$

$UCL = \bar{u} + 3\sqrt{\bar{u}/n}$
 $LCL = \bar{u} - 3\sqrt{\bar{u}/n}$

a(3)- Suppose the inspection unit is redefined as eight transmissions, design control chart for average number of nonconformities per unit.

The new sample is $n = 8/4 = 2$

n = new
old

Since this chart was established for average nonconformities per unit, the same control limits may be used.

n = 2 as per

$UCL = 1.6875 + 3\sqrt{1.6875/2} = 2.698$
 $CL = 1.6875$
 $LCL = 0$

b(3)- If the inspection unit is redefined as two transmissions, construct nc-chart.

$\bar{c} = \frac{\sum No. Hb}{m} = \frac{27}{16} = 1.6875$
 $n = 1/2 \Rightarrow n\bar{c} = 0.84375$
 $UCL = \bar{c} + 3\sqrt{\bar{c}} = 3.6$
 $LCL = \bar{c} - 3\sqrt{\bar{c}} = 0$

Q7. (16) Given the following (assume normally distributed quality characteristic):

(1) The $\bar{x}$ -R charts:

- The $\bar{x}$ chart: $UCL = 626$ $CL = 620$ $LCL = 614$
- The R chart: $UCL = 18.8$ $CL = 8.2$ $LCL = 0$

n = 4 specifications: 610 ± 15

(2) The $\bar{x}$ -s charts:

- The $\bar{x}$ chart: $UCL = 710$ $CL = 700$ $LCL = 690$
- The s chart: $UCL = 18$ $CL = 8$ $LCL = 0$

n = 4 specifications: 705 ± 15

1- For $\bar{x}$ -R charts (3): (5, 50)

Specification limits

a(4) What would be the estimate of the fraction nonconforming and process capability index?

$\sigma = \bar{R}/d_2 = 8.2/2.059 = 4$

$P(x > USL)$

$p = P(x < LSL) + P(x > USL)$
 $= \Phi\left(\frac{595 - 620}{4}\right) + 1 - \Phi\left(\frac{625 - 620}{4}\right)$
 $= \Phi(-6.25) + 1 - \Phi(1.25)$
 $= 0 + 1 - 0.8944 = 0.1056$

$C_p = \frac{USL - LSL}{6\sigma} = \frac{625 - 595}{6 \times 4} = 1.25$

UNIVERSITY OF JORDAN
Dept. of Industrial Engineering
Quality Control (Final Exam 4/6/09)
INSTRUCTOR: DR. AL-REFAIE, A.

NAME: _____

ID: _____

SR # _____

FINAL ANSWERS SHOULD BE PROVIDED WITH DETAILED CALCULATIONS

Q1. (12) Please fill in the blank the missing terms or phrases in the below table:

- ❖ The control chart detects only (1) causes. assignable
- ❖ The (2) chart is simply a frequency distribution of attribute data arranged by category. Pareto chart
- ❖ The (3) is a formal tool frequently useful in underlying potential causes. cause & effect diag.
- ❖ The (4) is a useful plot for identifying a potential relationship between two variables. scatter diag.
- ❖ (5) is simply the percentage of the specification band that the process uses up. $(\bar{X}_p) \times 100\%$
- ❖ The (6) is used when the sample size n is moderately large; i.e., 10 or greater. $\bar{X}$ -s charts
- ❖ The (7) is the number of time periods that occur until a signal is generated on the control chart. ATS
- ❖ The (8) is used when repeat measurement on the process differ only because of analysis error. Individual
- ❖ (9) is indicated when the plotted points tend to fall near or slightly outside the control limits. mixture
- ❖ The (10) is defined as the ratio of the number of nonconforming items in a population to the total number of items in that population. fraction non conforming
- ❖ If the process is out of control and capable, then the action taken to improve a process will be (11). SPC
- ❖ The (12) chart is used to control nonconformities on a product with variable inspection units. c-chart

1	assignable	7	ATS
2	Pareto chart	8	Individual - Moving range
3	cause & effect	9	mixture
4	Scatter diag.	10	fraction nonconform.
5	$\bar{X}_p \times 100\%$	11	SPC
6	$\bar{X}$ -s chart	12	c-chart

Q2. (2) A manufacturer used the p chart with $CL = 0.1$, $UCL = 0.19$, and $LCL = 0.01$ to control a process. If the 2-sigma limits are used, find the sample size for this chart. (6-18a)

$$UCL = p + 2\sqrt{p(1-p)/n}$$

$$\Rightarrow n = p(1-p) \left(\frac{2}{UCL - p} \right)^2 \Rightarrow n = 45$$

Kaizen Team

Q3(3) In designing a fraction nonconforming chart with center line at $p = 0.2$ and two-sigma control limits, (a) what is the sample size required to yield a positive lower control limit? (b) What is the value of n necessary to give a probability of 0.5 of detecting a shift in the process to 0.26? (6-14)

(1) $p = 0.2$ $L = 2$

$$\bar{p} - n > (1-p) \frac{L^2}{P}$$

$$n > 16$$

(2) $p = 0.26$

$$S = 0.26 \cdot 0.2 = 0.052$$

$$n = \left(\frac{L}{S} \right)^2 p(1-p) = \left(\frac{2}{0.052} \right)^2 (0.26)(1-0.26) = 178$$

Q4(3) Surface-finish defects in a small electric appliance occur at random with a mean rate of 0.1 defects per unit. Find the probability that a randomly selected unit will contain at most two surface-finish defects. (2-38)

$$P(X \leq 2) = 1 - P(X > 2)$$

$$= 1 - [P(X=0) + P(X=1)] = 1 - \left[\frac{e^{-0.1}}{0!} + \frac{e^{-0.1}}{1!} \right] = 0.999$$

Q5(8) Two different hardening processes A and B are used on samples of a particular alloy. Assume the hardness is normally distributed. Given that $\alpha = 0.05$ and

$$(\bar{x}_A = 147, s_A = 5.0, n_A = 10)$$

$$(\bar{x}_B = 149, s_B = 5.5, n_B = 10)$$

a(3) Test the hypothesis that the two variances are equal.

$$H_0: \sigma_1^2 = \sigma_2^2$$

$$H_1: \sigma_1^2 \neq \sigma_2^2$$

$$F_0 = \frac{s_1^2}{s_2^2} = 0.826$$

$$F_{\alpha/2}$$

$$1 - F_{\alpha/2, n_1-1, n_2-1}$$

$$0.248$$

$$4, 0.3$$

Fail to reject

b(3) Test the hypothesis that the mean hardness for process A is greater than the mean hardness for process B (assume equal variances).

$$H_0: \mu_1 = \mu_2$$

$$H_1: \mu_1 > \mu_2$$

$$s_p^2 = \frac{(n_1-1)s_1^2 + (n_2-1)s_2^2}{n_1+n_2-2}$$

$$s_p = 5.26$$

$$t_0 = \frac{\bar{x}_1 - \bar{x}_2}{s_p \sqrt{1/n_1 + 1/n_2}}$$

$$t_0 = -0.804$$

c(2)- Construct a 95 % confidence on the variance of process A.

$$t_{\alpha/2, n_1+n_2-2} = 1.734$$

$$\frac{(n-1)s^2}{\chi_{\alpha/2, n-1}^2} \leq \sigma^2 \leq \frac{(n-1)s^2}{\chi_{1-\alpha/2, n-1}^2}$$

$$\frac{9(5^2)}{19.02} \leq \sigma^2 \leq \frac{9(5^2)}{2.7} \quad 2/4$$

$$11.599 \leq \sigma^2 \leq 83.333$$



Kaizen Team

Q6. (9) An automobile manufacturer wishes to control the number of nonconformities in a subassembly area producing manual transmissions. The inspection unit is defined as four transmissions. The following 16 samples are collected (each of size 4).

$$\bar{c} = \bar{u} = \frac{\sum u_i}{m} = \frac{(\sum x_i/n)}{m}$$

$$= (27/4)/16 = 0.422$$

$$UCL = \bar{u} + 3\sqrt{\bar{u}/n}$$

$$LCL = \bar{u} - 3\sqrt{\bar{u}/n}$$

#	No. of nonconformities	#	No. of nonconformities
1	1	9	2
2	3	10	1
3	2	11	0
4	1	12	2
5	0	13	1
6	2	14	1
7	1	15	2
8	5	16	3

a(3)- Suppose the inspection unit is redefined as eight transmissions, design control chart for average number of nonconformities per unit.

The new sample is $n = 8/4 = 2$ inspection unit

Since this chart was established for average nonconformities per unit, the same control limits may be used.

sample size of 2 transmissions (2x16) $\bar{c} = 0.843$
 $UCL = 0.843 + 3\sqrt{0.843} = 2.1$
 $LCL = 0.843 - 3\sqrt{0.843} = 0$

b(3)- If the inspection unit is redefined as two transmissions, construct $\bar{c}$ -chart.

$\bar{c} = 27/16 = 1.6875$
 $n = 1/2 \Rightarrow n\bar{c} = 0.843$
 $UCL = \bar{c} + 3\sqrt{\bar{c}} = 1.6875 + 3\sqrt{1.6875} = 3.6$
 $LCL = \bar{c} - 3\sqrt{\bar{c}} = 1.6875 - 3\sqrt{1.6875} = 0$
 sample size of 2 transmission = 1 inspection unit

Q7. (16) Given the following (assume normally distributed quality characteristic):

(1) The $\bar{x}$ - R charts:

- The $\bar{x}$ chart: $UCL = 626$ $CL = 620$ $LCL = 614$

$n = 4$ specifications: 610 ± 15

- The R chart: $UCL = 18.8$ $CL = 8.2$ $LCL = 0$

(2) The $\bar{x}$ - s charts:

- The $\bar{x}$ chart: $UCL = 710$ $CL = 700$ $LCL = 690$

$n = 4$ specifications: 705 ± 15

- The s chart: $UCL = 18$ $CL = 8$ $LCL = 0$

1- For $\bar{x}$ - R charts (8): (5:50)

a(4) What would be the estimate of the fraction nonconforming and process capability index?

$$\hat{\sigma} = \bar{R}/d_2 = 8.2/2.059 \approx 4$$

$$\hat{p} = P(x < LSL) + P(x > USL)$$

$$= \Phi\left(\frac{595 - 626}{4}\right) + 1 - \Phi\left(\frac{625 - 626}{4}\right)$$

$$= \Phi(-7.75) + 1 - \Phi(-0.25) = 0.40129$$

$$C_p = \frac{USL - LSL}{6\sigma} = \frac{625 - 595}{6 \times 4} = 1.2553$$

Industrial Engineering Department
Quality Control - 96352
exam # 1

Saturday 29/3/2003
60 minutes

Name: علي محمد
Number: 0005557

Question 1: (fill in the spaces) (10 points)

1. Quality improvement is achieved through the reduction of variability in processes and products.
2. The sample average is a measure of central tendency.
3. The standard deviation is a measure of scatter, spread or variability.
4. The probability distribution of a random variable representing the number of defective units in a sample is binomial.
5. The probability distribution of a random variable representing the number of required samples until the third out of control sample point is detected is negative binomial (Pascal).
6. In acceptance sampling, the distribution of a random variable representing the number of defective units in a sample drawn from a lot of known size and percent defective is hypergeometric.
7. The probability that a point plots outside the control limits immediately after a shift in the process mean occurs is equal to $1 - \beta$.
8. The statistic that is plotted on a $\bar{X}$ -chart is $\bar{X}$.
9. The R-chart is used to monitor variability within a sample.
10. The $\bar{X}$ -chart is used to monitor variability among samples.

Question 2: (true / false) (10 points)

1. $\phi(2) < 1 - \phi(-2)$ ✓ $\phi(2) = 1 - \phi(-2)$
2. $\phi(3) > \phi(1)$ ✓
3. $\phi(1) + \phi(-1) = 1.00$ ✓
4. Type-I error is committed when one says that the process is out of control when it is actually in control. ✗
5. Type-II error is the probability that a point plots outside the control limits. ✗
6. The relationship $\alpha = 1 - \beta$ is only true when the process is in control. ✗ (no shift occurs) ($k=0$)
7. Quality improvement is achieved through the production of products with best quality. ✗
8. The power of the chart is the probability that a point plots outside the control limits immediately after a shift in the process mean occurs. ✓ ($1 - \beta$)
9. ARL is the average number of samples required until a point plots outside the control limits by chance. ✗
10. Control charts, design of experiments and acceptance sampling are all part of the statistical methods for quality improvement. ✓

Question 3: (multiple choice questions) (10 points)

1. A cause and effect diagram is used for:
 - a. Checking randomness of data.
 - b. Checking distribution of data.
 - c. ✓ Determining reasons for possible problems.
 - d. Determining the flow of a process.
2. Which of the following statements is true?
 - a. Type-II error is the probability that a point plots inside the control limits.
 - b. The relationship $\alpha = 1 - \beta$ is always true. ✓
 - c. ✓ Type-I error is the probability that a point plots outside the control limits.
 - d. All of the above.
3. The power of the chart is:
 - a. the probability of making type-II error.
 - b. ✓ the probability that a point plots outside the control limits immediately after a shift in the process mean occurs.
 - c. the average number of samples required to detect a shift in the process mean.
 - d. The ability of a chart to detect out of control conditions.
4. A value of a measurement that corresponds to the desired value for a quality characteristic is called:
 - a. lower specification limit
 - b. ✓ nominal value
 - c. upper specification limit
 - d. process mean

5. A histogram is used for:
- Checking randomness of data.
 - ☒ Checking the distribution of data.
 - Checking trends in data.
 - None of the above.
6. Which of the following is not part of the statistical methods for quality improvement?
- control charts
 - design of experiments
 - ☒ total quality management
 - acceptance sampling
7. Which of the following a control chart does not do?
- process correction
 - process monitoring
 - detection of possible problems
 - ☒ detection of non-random process behavior
8. The performance dimension of quality answers the following question:
- what does the product do?
 - ☒ will the product do the intended job?
 - is the product made exactly as the designer intended?
 - how long does the product last?
9. The reliability dimension of quality answers the following question:
- ☒ When does the product fail?
 - How often does the product fail?
 - How long does the product last?
 - How easy is it to repair the product?
10. Which of the following statements is true?
- Quality is directly proportional to variability.
 - ☒ Quality is inversely proportional to variability.
 - Quality means fitness for use.
 - (b) and (c).

Question 4: (10 points)

- i. A production process operates with 2% nonconforming output. Every hour a sample of 10 units is taken. If 1 or more nonconforming units are found, the process is stopped. What is the probability that the process will not be stopped on the next sample?

$$P(X=0) = \binom{10}{0} (.02)^0 (.98)^{10} = (.98)^{10}$$

~~X ~ Binomial (n=10, p=0.02)~~

- ii. What is the probability that at most 10% of the sample will be nonconforming?

$$P\left(\frac{X}{n} \leq .1\right) = P(X \leq 1) = P(X=0) + P(X=1) = (.98)^{10} + \binom{10}{1} (.02)^1 (.98)^9$$

$$= (.98)^{10} + 2 \times (.98)^9 = (.98)^9 (1 + 2 \times .02) = (.98)^9 (1.04)$$

Question 5: (10 points)

- i. A lot of size N=10 contains 3 nonconforming units. What is the probability that a sample of 3 units selected at random contains exactly one nonconforming unit?

Hypergeometric distribution

$$\binom{3}{1} \binom{7}{2} / \binom{10}{3}$$

$$P(1) = \frac{21}{120} = \frac{7}{40}$$

$$6 = \sqrt{16} = 4$$

- ii. If $X \sim N(\mu, \sigma^2 = 16)$. What is the value of μ if the probability that X is less than 32 is equal to 0.5?

$$P(X < 32) = 0.5$$

$$P\left(\frac{X - \mu}{\sigma} < \frac{32 - \mu}{4}\right) = 0.5$$

$$Z = 0 \rightarrow$$

$$\frac{32 - \mu}{4} = 0 \rightarrow \mu = 32$$

Question 6: (15 points)

The in-control model for a certain quality characteristic ($\bar{X}$) is given by $CL = 10$, $UCL = 13.09$ and $LCL = 6.91$ with 0.001 probability limits and $n = 4$.

- i. Estimate the process parameters μ and σ .

$$\mu_{\bar{X}} = CL = \mu_{process} = \bar{X} = 10$$

$$UCL = 13.09 = 10 + 3.09\sigma$$

$$UCL = CL + 3.09\sigma$$

$$LCL = CL - 3.09\sigma$$

$$6\bar{\sigma} = \frac{6\sigma_{process}}{\sqrt{n}}$$

$$6\bar{\sigma} = 6 = \frac{6\sigma}{\sqrt{4}}$$

$$\begin{matrix} 3.09 \\ 10.09 \end{matrix}$$

$$13.09 - 10 = 3.09\sigma \rightarrow 3.09 = 3.09\sigma \rightarrow$$

$$\boxed{\sigma = 1}$$

$$\boxed{6\sigma = 2}$$

- ii. What is the probability that a shift in mean to $\mu_{new} = 13.09$ will be detected immediately on the first sample following the shift?

$$\mu_{new} = \mu_{old} + k\sigma_{process} = 10 + k\sigma = 13.09 \rightarrow 10 + k(2) = 13.09$$

$$B = \Phi\left(\frac{13.09 - 10}{2\sqrt{4}}\right) - \Phi\left(\frac{6.91 - 10}{2\sqrt{4}}\right)$$

$$B = \Phi\left(\frac{3.09}{2}\right) - \Phi\left(\frac{-3.09}{2}\right)$$

$$2k = 3.09$$

$$k = 1.545$$

- iii. What is the average run length for this chart?

$$ARL = \frac{1}{1 - B}$$

$$B = \Phi(0) - \Phi(-0.118) = \Phi(0) = ?$$

$$1 - B = \text{probability that a shift occurs will be detected immediately.}$$

Question 7: (15 points)

An $\bar{X}$ -chart with 0.001 probability limits has been constructed to monitor a certain quality characteristic. The following two rules are used to determine if the process is out of control:

1. If one sample point plots outside the control limits.
2. If three consecutive sample points plot above the median.

$$\bar{Z} = \frac{\bar{X} - \mu}{\sigma}$$

- i. What is α_1 associated with rule (1)?

$$\alpha_1 = P(X > UCL) + P(X < LCL) = P\left(\frac{\bar{X} - \mu}{\sigma} > \frac{13.09 - 10}{2}\right) + P\left(\frac{\bar{X} - \mu}{\sigma} < \frac{6.91 - 10}{2}\right)$$

$$+ P\left(\frac{\bar{X} - \mu}{\sigma} < \frac{6.91 - 10}{2}\right) = P(Z > 3.09) + P(Z < -3.09)$$

$$[1 - \Phi(3.09)] + \Phi(-3.09) = 2\Phi(-3.09) = \alpha_1$$

- ii. What is α_2 associated with rule (2)?

$$Z(0.00135) = 3.09 \approx \alpha_1$$

$$\alpha_2 = (0.5)^3 = ?$$

- iii. Show that α -total associated with both rules is given by $1 - (1 - \alpha_1)(1 - \alpha_2)$.

Probability to $(1 - \alpha_1)$ that the point is in control limit (first rule)
to $(1 - \alpha_2)$ that the point is in control limit (second rule)

The probability that the process is in control is $(1 - \alpha_1)(1 - \alpha_2)$

that is in control is $1 - (1 - \alpha_1)(1 - \alpha_2)$

to be independent

— 3

Question 8: (10 points)

Consider the following data for a certain quality characteristic:

$$\sum \bar{X}_i = 500, \sum R_i = 50, m=25, n=4, d_2 = 2, d_3 = 0.9.$$

Construct appropriate $\bar{X}$ and R charts. with 3 σ limits.

$\bar{X}$ -chart.

$$CL = M\bar{X} = \bar{\bar{X}} = \frac{\sum \bar{X}}{25} = \frac{500}{25} = 20 \checkmark$$

$$UCL = CL + 3\sigma_{\bar{X}} = 20 + 3\left(\frac{1}{2}\right) = 23.5 \quad \checkmark$$

$$LCL = CL - 3\sigma_{\bar{X}} = 20 - 3\left(\frac{1}{2}\right) = 20 - 1.5 = 18.5 \quad \checkmark$$

$\bar{R}$ -chart

$$CL = \bar{R} = M_R = \frac{\sum R}{25} = \frac{50}{25} = 2$$


$$UCL = CL + 3\sigma_R = 2 + 3(0.9) = 2 + 2.7 = 4.7 \quad \checkmark$$

$$LCL = CL - 3\sigma_R = 2 - 3(0.9) = 2 - 2.7 = -0.7 \quad \checkmark$$

$\bar{X}$ -chart



$\bar{R}$ -chart



6 process

$$\sigma_{\bar{X}} = \frac{\sigma}{\sqrt{n}} = \frac{1}{\sqrt{4}} = \frac{1}{2}$$

$$\sigma_{\bar{R}} = \frac{\sigma}{\sqrt{n}} = \frac{1}{\sqrt{4}} = \frac{1}{2}$$

$$\bar{R} = \frac{\sum R}{25} = \frac{50}{25} = 2$$

$$d_2 = 2, d_3 = 0.9$$

$$6\sigma_{\bar{X}} = \frac{\bar{R}}{d_2} = \frac{2}{2} = 1$$

$$6\sigma_{\bar{R}} = \frac{\sigma}{d_3} = \frac{1}{2}$$

$$6R = d_3 6\sigma_{\bar{R}} = 0.9 \times 1 = 0.9$$

$$6R = (0.9)(1) = 0.9$$

24
18
20
15
20

Industrial Engineering Department
Quality Control - 96352
exam # 1

Saturday 25/3/2000
60 minutes

Name: Rana Saleh

Number: 984915


Question 1: (25 points)

I. Fill in the spaces:

1. Quality improvement is achieved through the reduction of variability in processes and products.
2. A value of a measurement corresponding to the desired value of a quality characteristic is called conformity nominal or target value.
3. The largest and smallest allowable values for a quality characteristic are called specification limits.
4. The sample average is a measure of central tendency.
5. The standard deviation is a measure of scatter spread.
6. The probability distribution of a random variable representing the number of defective units in a sample is binomial.
7. The probability distribution of a random variable representing the number of required samples until the third out of control sample point is detected is Pascal (Negative binomial).
8. The probability distribution of a random variable representing the number of defects in a square meter of carpet is Poisson distribution.
9. In acceptance sampling, the distribution of a random variable representing the number of defective units in a sample drawn from a lot of known size and percent defective is hyper geometric.
10. The relationship $\alpha = 1 - \beta$ is only true when process is in control actually no shift in mean or standard deviation.
11. The probability that a point plots outside the control limits immediately after a shift in the process mean occurs is $1 - \beta$.

II. True / False:

1. $\phi(3) = 1 - \phi(-3)$ ✓
2. $\phi(3) < \phi(2)$ X ✓
3. $\phi(3) + \phi(-3) = 0.0027$ X ✓ = 1
4. Type-II error is the probability that a point plots inside the control limits. X ✓ / process is out of control
5. The relationship $\alpha = 1 - \beta$ is always true. X ✓
6. Type-I error is the probability that a point plots outside the control limits. ✓ ✓
7. Quality improvement is achieved through the production of products with best quality. X ✓
8. The power of the chart is the ability of a control chart to detect out of control conditions ✓
9. ARL is the average number of samples required to detect a shift in the process mean. ✓ ✓
10. ATS is the average time until a shift in process mean is detected. ✓ ✓
11. Control charts, design of experiments and acceptance sampling are all part of the statistical methods for quality improvement. ✓ ✓
12. Control charts are designed for the purpose of process correction. X ✓
13. The performance dimension of quality answers the question "will the product do the intended job?" ✓ ✓



Question 2: (20 points)

$$p = 0.02$$

- i. A production process operates with 2% nonconforming output. Every hour a sample of 10 units is taken. If 1 or more nonconforming units are found, the process is stopped. What is the probability that the process will not be stopped on the next sample?

X : # of non conforming parts in sample (n=10) $X \sim \text{binomial}(p=0.02, n=10)$
process not be stopped mean $p(X=0)$

$$p(X=0) = (0.98)^{10} \checkmark$$

- ii. For the same process in part (a), what is the probability that the fraction nonconforming of the next sample is less than 0.1?

$$\hat{p} = \frac{X}{n} \Rightarrow X = \hat{p}n$$

$$\hat{p} = p\left(\frac{X}{n} < 0.1\right) = p(X < 1) = p(X=0) = (0.98)^{10} \checkmark$$

- iii. A lot of size $N=10$ contains 3 nonconforming units. What is the probability that a sample of 3 units selected at random contains exactly one nonconforming unit?

X : # of non conforming units in sample of size 3


$$p(X=1) = \frac{\binom{3}{1} \binom{7}{2}}{\binom{10}{3}} = ? \quad \leftarrow \text{10}$$

- iv. If $X \sim N(\mu, \sigma^2 = 16)$. What is the value of μ if the probability that X is less than 32 equals 0.5?

$$p(X < 32) = 0.5$$

$$p\left(z < \frac{32 - \mu}{\sqrt{16}}\right) = 0.5 \checkmark$$

$$\frac{32 - \mu}{\sqrt{16}} = 0 \Rightarrow \boxed{\mu = 32}$$



$$\mu = 32$$

Question 3: (20 points)

The in-control model for a certain quality characteristic ($\bar{x}$) is given by $CL = 10$, $UCL = 13.09$ and $LCL = 6.91$ with 0.001 probability limits and $n = 4$.

Estimate the process parameters μ and σ .

$$\textcircled{1} \mu = CL = 10$$

$$UCL = \mu + 3.09 \sigma_{\bar{x}}$$

$$13.09 = 10 + 3.09 \sigma_{\bar{x}} \checkmark$$

$$3.09 = 3.09 \sigma_{\bar{x}} \Rightarrow \sigma_{\bar{x}} = 1$$

$$\sigma_{\bar{x}} = \sqrt{n} \cdot \sigma_{\bar{x}}$$

$$\boxed{\sigma = 2} \checkmark$$

$$6.91 = \mu - 3.09$$

$$13.09 = \mu + 3.09$$

$$20.00 = 2\mu$$

$$\textcircled{1} \boxed{10 = \mu}$$

What is the probability that a shift in mean to $\mu_{\text{new}} = 13.09$ will be detected on the first sample following the shift?

$$\mu_{\text{new}} = \mu_{\text{old}} + K \sigma_p$$

$$13.09 = 10 + K(2) \Rightarrow K = 3.09/2$$

$$\beta = p(\text{Point plot in side control limit} / \text{process is out of control})$$

$$\beta = \Phi\left(\frac{3.09 - \frac{3.09}{2}(2)}{0}\right) - \Phi\left(\frac{-3.09 - \frac{3.09}{2}(2)}{0}\right)$$

$$\beta = 0.5 \checkmark$$

$$p(\text{shift will be detected on first sample}) = p(\text{point is out control limits}) = 1 - \beta = 0.5$$

0.00153
0.99847

Question 4: (15 points)

An $\bar{x}$ control chart with 3-sigma limits has been constructed to monitor a certain quality characteristic. The following two rules are used to determine if the process is out of control:

- If two consecutive sample points plot outside the control limits.
- If three consecutive sample points plot above the center line.

i. What is α_1 associated with rule (a)?

$$\alpha_1 = P(\text{2 points plot outside control limit} / \text{process is in control})$$

$$= P(\text{First point plot outside / in-control}) * P(\text{second point plot outside / in-control})$$

$$\alpha_1 = P(X > UCL) + P(X < LCL) = (0.0027) + (0.0027) = 0.0054$$

$$\alpha_1 = 0.0054$$

ii. What is α_2 associated with rule (b)?

$$\alpha_2 = P(\text{3 points above center line} / \text{process is in control}) = 0.5$$

$$\alpha_2 = P(P_1 \text{ plots above CL} / \text{in-control}) * P(P_2 \text{ plots above CL} / \text{in-control}) * P(P_3 \text{ plots above CL} / \text{in-control})$$

$$\alpha_2 = (0.5)^3 = 0.125$$

iii. What is overall α associated with both rules?

$$\alpha = 1 - (1 - \alpha_1)(1 - \alpha_2)$$

$$= 1 - ((1 - 0.0054)(1 - 0.125)) = 0.1247$$

Question 5: (20 points)

Thirty samples each of size 9 have been collected. $\sum \bar{x}_i = 2700$ and $\sum R_i = 120$.

Construct the in control model for both $\bar{x}$ and R charts based on 3-sigma limits.

R-chart

$$UCL = (120/30) + D_4 = 4 + 1.816(120/30) = 7.264$$

$$CL = 120/30 = 4$$

$$LCL = (120/30) - D_3 = 4 - 0 = 4$$

If the R-chart was in control, estimate the process standard deviation.

$$\bar{R} = d_2 \sigma_p$$

$$4 = (2.97) \sigma_p \Rightarrow \sigma_p = 4 / 2.97 = 1.347$$

GOOD LUCK

$\bar{x}$ -chart

$$UCL = 90 + A_2 \bar{R} = 90 + (0.337)(4) = 91.348$$

$$\bar{X} = CL = 2700/30 = 90$$

$$LCL = 90 - (0.337)(4) = 89.652$$

$$\begin{array}{r} 0.337 \\ 4 \\ \hline 1.348 \end{array}$$

Kaizen Team


Quality Control (Quiz 1)

Student Name: ~~_____~~ ID: 70707 SR#: 42

1% = The traditional definition(s) of quality is that
1. Collection of desirable ~~Q.C.H.~~ ✓
2. Fitness for use. ✓

1% = Quality costs are defined as: Categories of costs that are associated with producing, identifying, avoiding or repairing products that not meet requirements

2% = Illustrate the phase diagram of the use of quality-engineering methods:



2% = A random sample of 50 units is drawn from a production process every two hours. What is the probability that the estimated fraction nonconforming is at most 2% if the fraction nonconforming is really 0.04.

$n=50$ $p=0.04$
 $P(\hat{p} \leq 0.02)$ $P(\hat{p} \leq 0.04)$ $\hat{p} = \frac{X}{n} \rightarrow 0.04 \geq \frac{X}{50}$

$P(X \leq 2) = P(X=0) + P(X=1) + P(X=2)$
 $\binom{50}{0} (0.04)^0 (0.96)^{50} + \binom{50}{1} (0.04)^1 (0.96)^{49} + \binom{50}{2} (0.04)^2 (0.96)^{48} = 0.364 + 0.3716 + 0.186 = 0.9214$

2% = A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the lower specification limit such that only 0.5% of the bulbs will not exceed the limit.

$P(X \leq \frac{a-\mu}{\sigma}) = 0.005$ $1 - 0.005 = 0.995$

$\frac{a-\mu}{\sigma} = 2.58$
 $\frac{a-5000}{50} = 2.58 \Rightarrow a = 5129$
 $LSL = \mu - 4\sigma = 10000 - 5129 = 4871$

2% = Surface-finish defects in a small electric appliance occur at random with a mean rate of $\lambda = 0.1$ defects per unit. Find the probability that a randomly selected unit will contain no surface-finish defects.

$P(X=0) = \frac{e^{-\lambda} \lambda^0}{0!} = e^{-0.1} = 0.9048$

$P(\hat{p} \leq 0.02) = P(\hat{p} \leq 0.04)$

Kaizen Team

Quiz (1) Quality Control

Date: 16/10/2008

Name: ~~Ali Al-Hadi~~

ID: ~~10101010~~

10/10

Q(1) What is the traditional definition of quality? Mention three quality-engineering techniques used for reducing variability.

Fitness for Use

1) Design of Experiments

2) Control Charts

✓ 3) acceptance Sampling

Q(2) A production process operates with % 2 nonconforming output. Every hour a sample of 20 units of product is taken, and the number of nonconforming units counted. If one or more nonconforming units are found, the sample is rejected.

$$p = 0.02$$

$$n = 20$$

1- Calculate the probability of rejecting the sample.

$$P(X \geq 1) = 1 - P(X < 1)$$

2

$$1 - P(X=0) = 1 - \binom{20}{0} (0.02)^0 (0.98)^{20} = 0.3323$$

2- Using the poisson approximation, calculate the probability of detecting at least one nonconforming component. Is this approximation satisfactory? Why or why not?

$P < 0.1$ → the approx. is satisfactory

$$\lambda = np = 20(0.02) = 0.4$$

2

$$P(X \geq 1) = 1 - P(X < 1) = 1 - \frac{e^{-0.4} 0.4^0}{0!} = 1 - 0.67 = 0.33$$

Q(3) let x_1, x_2, x_3 , and x_4 are exponential with parameter $\lambda = 3$ and independent. If y is defined as the sum of the four distributions.

(a) What is the distribution of y ? Write the density function, $f(y)$.

y is Gamma distribution with $\lambda = 3$ & $r = 4$

2

$$f(y) = \frac{\lambda^r y^{r-1} e^{-\lambda y}}{\Gamma(r)} = \frac{3^4 y^{4-1} e^{-3y}}{(4-1)!}$$

(b) Calculate the mean and variance for the distribution in part (a).

2

$$\text{Mean} = \frac{r}{\lambda} = \frac{4}{3} = 1.33\bar{3}$$

$$\text{Var} = \frac{r}{\lambda^2} = \frac{4}{3^2} = \frac{4}{9} = 0.44\bar{4}$$

Quality Control
(Quiz 1)

(2009) 2nd semester..

8/10

Student Name: ---

ID: ---


SR#: ---

1 % = The modern definition of quality is that Quality is inversely proportional to variability

1 % = There are two general aspects of fitness for use:

- (1) quality of design
- (2) quality of conformance

2% = Illustrate the application of quality-engineering techniques for systematic reduction of process variability:



3 % = A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the upper specification limit such that only 0.5 % of the bulbs will exceed the limit.

$$\mu = 5000, \sigma = 50$$

$$P(X > USL) = 0.005 \Rightarrow P(X \leq USL) = 1 - 0.005 = 0.995$$

$$P(Z \leq \frac{USL - \mu}{\sigma}) = 0.995$$

$$Z \leq 2.58$$

$$\frac{USL - 5000}{50} = 2.58$$

$$USL = 5129$$

2 % = A random sample of 25 units is drawn from a production process every two hours.

What is the probability that the estimated fraction nonconforming is at least 4 % if the fraction nonconforming is really 25 %. Binomial distribution

$$n = 25$$

$$P(\hat{p} \geq 0.04) = P\left(\frac{X}{n} \geq 0.04\right) = P\left(\frac{X}{25} \geq 0.04\right) = P(X \geq 1)$$

$$= 1 - P(X \leq 0) = 1 - \left(\sum_{x=0}^0 \binom{25}{x} (0.25)^x (0.75)^{25-x}\right)$$

$$= 1 - P(X=0) = 1 - P(0) = 0.99924$$

2% = Surface-finish defects in a small electric appliance occur at random with a mean rate of 0.1 defects per unit. Find the probability that a randomly selected unit will contain at least one surface-finish defects.

$$\lambda = 0.1$$

$$P(X \geq 1) = 1 - P(X < 1) = 1 - P(0)$$

$$= 1 - \frac{e^{-0.1} (0.1)^0}{0!} = 1 - 0.9048$$

$$P(X \geq 1) = 0.0952$$

Q2: (4 pts) The time to wear out of a cutting tool edge is distributed normally with $\mu = 2.8$ and $\sigma = 0.6$ hr.

(a) What is the probability that the tool will wear out in less than 1.5 hr?

$$P(X < 1.5) = P\left(Z_0 < \frac{1.5 - 2.8}{0.6}\right) = P(Z_0 < -2.33) = 0.0099$$

(b) How often should the cutting edges be replaced to keep the failure rate less than 10 % of the tools?

$$\mu = 1/\lambda \Rightarrow \lambda = 0.357$$

Q3: (4 pts) The number of small business that fail each year is known to have a Poisson distribution with mean of 16. Find the probability that in a given year there will be no more than 18 small business failures using normal approximation. Is the approximation satisfactory? Why? Why not?

$$\sigma^2 = \mu = 16 = \lambda \quad P(X \leq 18) = P\left(Z_0 \leq \frac{x - \mu}{\sigma}\right)$$

$$= P(Z_0 \leq \frac{18 - 16}{4}) = P(Z_0 \leq 0.5) = 0.69146$$

16 $\geq$ 15 $\therefore$ Yes satisfactory

Q4: (8 pts) The variabilities of the service times of two bank tellers are of interest. Their supervisor wants to determine whether the variance of service time for the first teller is greater than that for the second. A random sample of 8 observations from the first teller yields a sample average of 3.4 minutes and a sample standard deviation of 1.8. A random sample of 10 observations from the second teller yields a sample average of 2.5 minutes and a sample standard deviation of 0.9 minutes.

(a) Can we conclude that the standard deviation of the service is greater for the first teller than the second teller? Use a level of significance α of 0.05.

$$n_1 = 8, \bar{x}_1 = 3.4, s_1 = 1.8 \quad n_2 = 10, \bar{x}_2 = 2.5, s_2 = 0.9$$

$$H_0: \sigma_1^2 = \sigma_2^2 \quad H_1: \sigma_1^2 > \sigma_2^2 \quad F_{0.05, 7, 9} = 4.2$$

$$F_{\text{calc}} = \frac{s_1^2}{s_2^2} = \frac{1.8^2}{0.9^2} = 4$$



(b) Test the hypothesis that the second bank teller provides larger mean service time than the first teller.

$$H_0: \mu_1 = \mu_2$$

$$H_1: \mu_1 < \mu_2$$

$$t = \frac{(\bar{x}_1 - \bar{x}_2) - (\mu_1 - \mu_2)}{\sqrt{\frac{s_1^2}{n_1} + \frac{s_2^2}{n_2}}} = \frac{3.4 - 2.5}{\sqrt{\frac{1.8^2}{8} + \frac{0.9^2}{10}}} = 1.291$$

$$t_{\alpha/2, N} = t_{0.05, 17} = 1.734$$

$$-t_{\alpha/2, N} = -1.734$$

(c) What is the approximate p-value in part (b).

$$\text{lower} \rightarrow \Phi(t_0) = \Phi(1.291)$$

if $\alpha > \text{p-value} \rightarrow$ we reject

1

tolerance limits $q:4$ $a:2$

unit $\rightarrow$ $\bar{x}$ -chart p.315

Q4 (10). Samples each of size seven have been collected to establish control over a process. The following data were collected:

$$\bar{m} = \frac{2100}{30} = 70$$

$$\sum_{i=1}^{30} \bar{x}_i = 2700$$

$$\sum_{i=1}^{30} R_i = 120$$

$$\bar{R} = \frac{120}{30} = 4$$

a:2 Calculate the natural tolerance limits

$$UCL = \bar{m} + 3\sigma = 70 + 3(1.479) = 94.437$$

$$CL = \bar{m} = 70$$

$$LCL = \bar{m} - 3\sigma = 70 - 3(1.479) = 85.563$$

b:2 Suppose an s chart were desired. What would be the 3 sigma control limits and centerline?

$$C_4 = 0.9594$$

$$\hat{\sigma} = \bar{R} / C_4 = 4 / 0.9594 = 4.179$$

$$UCL = B_4 \bar{R} = 2.67$$

$$B_3 = 0.118$$

$$B_4 = 1.882$$

$$P_{2.53}$$

$$CL = \bar{R} = 4.179$$

$$LCL = B_3 \bar{R} = 0.167$$

c:2 If the process mean shifts to 85. What is the probability detect the shift by the fourth sample. $UCL = 91.7$ $LCL = 88$

$$P(LCL < \bar{X} < UCL) = P\left(\frac{88 - 85}{1.48/\sqrt{7}} < Z < \frac{91.7 - 85}{1.48/\sqrt{7}}\right) = 0$$

$$P(\text{detect by 4th sample}) = 1 - \beta = 1 - 0 = 1$$

d:2 Calculate the alpha error using the $\bar{x}$ and R charts.

$$\sigma = \bar{R} / d_2 \sqrt{n} = 0.559 \rightarrow \text{very small}$$

$$P(88.325 < \bar{X} < 91.67) = 1 - [1 - P(\bar{X} \leq 88.32) + P(\bar{X} \leq 91.67)]$$

$$= 1 - [1 - P(Z \leq \frac{88.32 - 70}{0.559}) + P(Z \leq \frac{91.67 - 70}{0.559})] = 0.9998$$

e:2 What is the average run length using an out of control s chart.

$$ARL = \frac{1}{1 - \beta} = \frac{1}{1 - 0} = 1$$

Q5(4). The number of nonconformities in carpets is determined for 20 samples, but the amount of carpets inspected for each sample varies. Suppose that the number of nonconformities is observed per 100 m². The total number of nonconformities is calculated 192. The total number of inspection units is 41. Assume Average Sample

a. Calculate the 3 sigma control limits and centerline.

$$\bar{u} = \frac{192}{41} = 4.7$$

$$n = \frac{\text{total}}{m}$$

$$n = 41/20$$

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$$

$$UCL = 4.7 + 3\sqrt{\frac{4.7}{2.05}} = 9.2171$$

$$CL = \bar{u}$$

$$LCL = 4.7 - 3\sqrt{\frac{4.7}{2.05}} = 0.1486$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$$

b. Suppose the two samples are found out of control with number of nonconformities of 20 and 10, respectively. The assignable cause of the first sample is determined and eliminated, but the cause of the second sample is considered to be occurred by chance. Determine the revised 3 sigma centerline and control limits.

$$\bar{u} = \frac{172}{37} = 4.65$$

$$UCL = 4.65 + 3\sqrt{\frac{4.65}{n_1}}$$

$$CL = 4.65$$

$$n = \frac{37}{19} = 1.9473$$

$$LCL = 4.65 - 3\sqrt{\frac{4.65}{n_2}}$$

$$LCL = 1.88182$$

Q6(6). An assembled product consists of two parts. The first part is inserted in the second part with some clearance. The parts are produced in different machines and are assembled at random. Control charts are maintained on each dimension for the range of each sample of 5 sample size. 20 samples for the first part and 10 samples for the second part are used for range control chart. Given

$$\sum_{i=1}^{20} R_{1i} = 18.608$$

$$\sum_{i=1}^{10} R_{2i} = 6.978$$

$$C = \mu_2 - \mu_1$$

If it is desired that the probability of a smaller clearance than 0.09 should be 0.005.

a:2 Assuming that the dimensions are normally distributed, what is the distance between the average dimensions should be specified.

$$C = \mu_1 - \mu_2 \quad p(C < 0.09) = 0.005$$

$$Z = -2.58 = \frac{0.09 - \Delta}{\sigma}$$

$$\Delta = 2.326$$

$$\sigma = \sqrt{\frac{R_1^2}{d_2 n_1} + \frac{R_2^2}{d_2 n_2}} = \sqrt{\frac{(18.608)^2}{2.326 \cdot 20} + \frac{(6.978)^2}{2.326 \cdot 10}} = 0.179$$

$$\Delta = 0.09 - (-2.58 \cdot 0.179) = 0.557$$

$$\Delta = 0.667$$

b:2 Calculate the standard deviation for the assembled product.

$$\sigma_1 = 0.03204 \quad \sigma_2 = 0.01196$$

$$\sigma = \sqrt{\sigma_1^2 + \sigma_2^2} = \sqrt{0.001027 + 0.000143} = 0.034$$

c:2 If the clearance should be less than 0.1, how much will the fraction of nonconforming assemblies if the estimated means difference from the parts control charts is 0.09.

$$p(C > 0.1) = p\left(\frac{\bar{X} - \bar{Y}}{\sigma} > \frac{0.1 - 0.09}{0.034}\right) = p(Z > 0.29) = 0.508$$

Q7(5). A process is in control with $\bar{x} = 199$ and $R = 3.5$ obtained with a sample size of 4. Specifications are 200 $\pm$ 8. Assume the quality characteristic is normally distributed.

a:0.5 Estimate the potential process capability

$$C_p = \frac{USL - LSL}{6\sigma} = \frac{208 - 192}{6 \cdot 1.5696} = 1.5696$$

b:0.5 Estimate the actual process capability

$$C_{pk} = \min \left\{ \frac{208 - 199}{3 \cdot (1.7)}, \frac{199 - 192}{3 \cdot (1.7)} \right\} = 1.373$$

c:2 How much improvement could be made in process performance if the mean could be centered at the nominal value?

$$C_{pkm} = 1.1832 \quad \text{after centering} \quad C_p = C_{pk} = C_{pkm} = 1.5696$$

d:2 Suppose you want to increase the sensitivity to mean shift, calculate the proper process capability index.

$$C_{pkm} = \frac{C_{pk}}{\sqrt{1 + \frac{(\bar{x} - \mu)^2}{\sigma^2}}} = \frac{1.373}{\sqrt{1 + \frac{(199 - 200)^2}{1.7^2}}} = 1.183$$

$$\bar{x} = 199$$

$$R = 3.5$$

$$n = 4$$

$$USL = 208$$

$$LSL = 192$$

$$\sigma = 1.5696$$

$$\sigma = 1.5696$$

$$\sigma = 1.5696$$

Q5: (5 pts) The tuft bind strength of a synthetic material used to make carpets is known to have a mean of 50 kg and a standard deviation of 10 kg. If a sample of size 36 is randomly selected. Use a level of significance α of 0.05. $\mu = 50, \sigma = 10, n = 36, \alpha = 0.05$

(a) What is the probability that the sample mean will be less than 52.5 kg?

$$P(\bar{X} \leq 52.5) = P\left(Z \leq \frac{52.5 - 50}{10/\sqrt{36}}\right) = P(Z \leq 1.5) = 0.93319$$

(b) Construct a 95 % upper-sided confidence interval on the mean tuft bind strength. $z_{0.05} = 1.645$

$$\mu \leq \bar{X} + z_{\alpha} \sigma / \sqrt{n}$$

$$\mu \leq 52.5 + 1.645 \times 10 / \sqrt{36} = 55.24$$

$$\mu \leq 55.24$$

(c) If the true mean is 48 kg, what will be the consumer's risk? $\beta = 1 - \phi\left(\frac{50 - 48}{10/\sqrt{36}}\right) = 1 - \phi(0.76) = 0.77557$

$$\beta = \phi\left(\frac{50 - 48}{10/\sqrt{36}}\right) = \phi(0.76) = 0.77557$$

Q6: (4 pts) An automated machine is used to fill bottles with liquid detergent. A random sample of 20 bottles results in a sample variance of fill volume of 0.0153 (fluid ounces)². If the variance of fill volume exceeds 0.01 (fluid ounces)², an unacceptable proportion of bottles will be underfilled or overfilled.

(a) Is there evidence in the sample data to suggest that the manufacturer has a problem with underfilled or overfilled? Use α of 0.05, and assume that fill volume has a normal distribution?

$$H_0: \sigma^2 = 0.01$$

$$H_1: \sigma^2 > 0.01$$

$$\chi^2_{\alpha, n-1} = \frac{19 \times 0.0153}{0.01} = 29.07$$

$$\chi^2_{1-\alpha, n-1} = \chi^2_{0.95, 19} = 10.12$$



$\therefore$ fail to reject

(b) Construct a 95 % lower-sided confidence interval on the standard deviation of fill volume.


$$\frac{(n-1)s^2}{\chi^2_{1-\alpha, n-1}} \leq \sigma^2 = \frac{19 \times 0.0153}{10.12} = 0.287$$

$$0.0287 \leq \sigma^2$$

$$0.169 \leq \sigma$$

$$\sigma < \sigma^2 < \sigma$$

Q2: (3 pts) Illustrate chance and one assignable cause of variations. p. 182



Q3: (3 pts) The stem and leaf and the histogram provide visual impression about ^{visual display of 3 properties} ~~visual display of 3 properties~~ of sample data, whereas the sample average and standard deviation provide ^{quantitative information} ~~quantitative information~~ about features of data such as location, spread or variability, departure from symmetry. The box plots displays several important features of data such as location, spread or variability, departure from symmetry. ^{quantitative information} ~~quantitative information~~ about features of data such as location, spread or variability, departure from symmetry.

Q4: (9 pts) The length of a mechanical part is known to have a normal distribution with a mean 100 mm and a standard deviation of 2mm.

$$\mu = 100 \quad \sigma = 2$$

(a) What proportion of the parts will be above 103.3mm?

$$\begin{aligned} p(X > 103.3) &= 1 - p(X \leq 103.3) \\ &= 1 - p\left(Z \leq \frac{103.3 - 100}{2}\right) \\ &= 1 - \Phi(1.65) \\ &= 0.04947 \end{aligned}$$

(b) If a sample size 4 is randomly selected, what is the probability that the sample mean will be less than 101mm?

$$\begin{aligned} n &= 4 \\ \mu &< 101 \\ p(X < 101) &= p\left(Z < \frac{X - \mu}{\sigma/\sqrt{n}}\right) = p\left(Z < \frac{101 - 100}{2/\sqrt{4}}\right) = p(Z < 1) \\ &= 0.84134 \end{aligned}$$

(c) It is important that not many of the parts exceed the desired length. If the manager stipulates that no more than 5% of the parts should be oversized, what specification limit should be recommended?

$$\begin{aligned} p(X > 0.05) \\ &\text{chi-square dist.} \\ \chi^2 &< \frac{(n-1)s^2}{\sigma^2} \\ \chi^2 &= \frac{(3)2}{0.35} = 17.1 \end{aligned}$$

Sorry ~~for~~ for not giving the final

answer But there was no time.

Q5: (9 pts) Consider a lot of 100 parts, of which 94 are conforming. If a sample of 4 parts is selected,

(a) What is the probability of obtaining 2 nonconforming items? $N=100$ $D=6$ $n=4$

$x=2$ hyper-geometric

$$p(x=2) = \frac{\binom{4}{2} \binom{100-94}{4-2}}{\binom{100}{4}}$$

(b) If a binomial approximation is used, what is the required probability in part (a)? Is the approximation satisfactory?

$p = \frac{D}{N} = \frac{6}{100} = 0.06$
 $p(x=2) = \binom{4}{2} (0.06)^2 (0.94)^{4-2} = 0.11136$
 $p = 0.06 < 0.1$ not satisfactory

(c) If a Poisson distribution is used, calculate the probability in part (b). Is the approximation satisfactory?

$\lambda = np = 4 \times 0.06 = 0.24$
 $p(x=2) = \frac{e^{-\lambda} \lambda^x}{x!} = \frac{e^{-0.24} (0.24)^2}{2!} = 0.0276$
 $0.24 < 0.5$ not satisfactory

Q6 (12 pts) A component is known to have an exponential time-to-failure distribution with a mean life of 10,000 hours.

(a) What is the probability of the components lasting at least 8000 hours? $\lambda = 10,000$

$p(x \geq 8000) = 1 - p(x < 8000)$
 $= 1 - (1 - e^{-\lambda x}) = e^{-\lambda x} = e^{-10,000 \times 8000} = 0.3212$

(b) If the component is in operation at 9000 hours, what is the probability that it will last another 6000 hours?

$\int_0^{\infty} \lambda e^{-\lambda x} dx = 1$
 $\lambda = 10,000$

(c) Two such components are put in parallel, so that the system will be in operation if at least one of the components is operational. What is the probability of the system being operational for 12000 hours? Assume that the components operate independently.

$p(x=1) = 1 - e^{-\lambda x} = 1 - e^{-12000(1)} = 0.9999$
 $p(x=2) = 1 - e^{-\lambda x} = 1 - e^{-12000(2)} = 1$
 $P(X=1) + P(X=2) = 0.9999 + 1 = 1.9999$

(d) If the two components are operating in a system standby redundant system. Calculate the mean and standard deviation of system life.

$\mu = \frac{1}{\lambda} = \frac{1}{1200} = 8.3 \times 10^{-4}$

$\sigma = \sqrt{\frac{1}{\lambda^2}} = \sqrt{\frac{1}{1200^2}} = 8.3 \times 10^{-5}$