




QC

PAst papers

عندما تطمح في شيء وتوسعى جادا في الحصول
عليه.. فإن العالم بأسره يكون في صفك
باولو كويلو

QC

Q (1:10 pts) Please state whether the following is true or false (T/F), underline the false part then correct it:

1. How easy it is to repair the product? refers to durability. (X) Serviceability
2. The sensitizing rules are also called the zone rules. (X) the Western Electric rules
3. Traditional definition of quality is fitness for use. (✓) -----
4. Taste and appearance are examples of sensory critical-to-quality characteristics. (✓) -----
5. Design of experiment technique is the most efficient tools in reducing variability. (✓) -----
6. Product inspection and test is an example of appraisal costs. (✓) -----
7. Liability is an example of external failure costs. (✓) -----
8. Prevention costs are those associated with efforts in design and manufacturing that are directed toward the prevention of nonconformance. (✓) -----
9. In statistical six-sigma, the fraction nonconforming is 0.002 ppm. (X) defective 
10. A histogram is more compact summary of data than a stem-and-leaf plot. (✓) -----
11. The box-plot is a graphical display that simultaneously several important features (location, spread, etc) of the data. (✓) -----
12. The control limit contains target and two control limits. (X) control chart - CL → (control chart) (center line CL)
13. The specification limits are used to decide about product acceptance or rejection. (✓) -----
14. There is no mathematical relationship between specification limits and control limits. (✓) -----
15. The rational subgroup concept means that the chance for differences between subgroups will be maximized, while the chance for differences within subgroup will be minimized. (✓) -----
16. Random sampling is performed by taking each sample of units of product that are representative of all units that have been produced since the last sample was taken. (✓) -----
17. A run of length eight or more points has a very low probability of occurrence in a random sample of points. (✓) -----
18. Check sheet is simply a frequency distribution of attribute data arranged by category. (X) Pareto chart
19. The defect concentration diagram is analyzed to determine whether the location of the defects on unit conveys any useful information about the potential causes of the defects. (✓) -----
20. A process operating under the existence of assignable causes is said to be out-of-control. (✓) -----

10

The life $\sim N(7000, (1000)^2)$


$\mu = 7000$

~~11.4~~

Q (4: 4 pts) The specification on an electronic component in a target-acquisition system are that life is must be between 5,000 and 10,000 hr. The life is normally distributed with mean 7000. The manufacturer realizes a price of \$10 per unit processed. However, defective units must be replaced at a cost of \$5 to the manufacturer. The standard deviation is 1000 hr.

$n = 7000$

$\lambda = 5000$



$\sigma^2 = 10^6$

- Calculate the expected profit when 5,000 are sold.

$* 10 \times 5000 = \$50,000$

$P(X < 5000)$
 $P(Z < -2)$

$50,000 - 568.75$

$= 49,431.25$

the expected profit

$1/2$

$= 0.02275$ the prop to be defective.

$\Rightarrow 5000 \times 0.02275 = 113.75 \Rightarrow$ may be ~~were~~

$50 \times 113.75 = 568.75$ Defective

- If a sample of 40 units are selected with the same mean and standard deviation. What is the probability that mean life will exceed 10,000?

$n = 40$ μ & σ are the same.

$P(X > 10000) = 1 - P(X \leq 10000) = 1 - P(Z \leq \frac{10000 - 7000}{1000})$

$= 1 - P(Z \leq 3) = 1 - 0.998650 = 0.00135$

Q (5: 5 pts) A system is composed of 4 electronic units that are exponentially distributed with mean life to failure of 500 hours.

$r = 4$

$\mu = \frac{1}{\lambda} = 500$

$\lambda = \frac{1}{500} = 0.002$

- What is the probability the unit will fail before its 500 hours. use expo. dist.


$F(a) = F(500) = 1 - e^{-\lambda(500)}$

$= 1 - e^{-0.002(500)} = 0.63212$



- What is the probability that the unit will operate 400 if it operated 300 hours.

$F(a) = F(400) = 1 - e^{-0.002(400)} = 0.5507$



- What is the probability that the system will survive 500 hours if the units are arranged in a stand-by configuration? use Gamma dist.

$r = 4$

$\lambda = 0.002$

$R(500) = \sum_{k=0}^{r-1} \frac{e^{-\lambda t} (\lambda t)^k}{k!}$

$= \frac{e^{-1} (1)^0}{0!} + \frac{e^{-1} (1)^1}{1!} + \frac{e^{-1} (1)^2}{2!} + \frac{e^{-1} (1)^3}{3!} = 0.3679 + 0.18395 + 0.122$

23.5
30

3.5 Q (1: pt 4) Please fill the blank with proper terms or statements.

- Quality is inversely proportional to Variability.
- Appraisal costs are those costs associated with measuring, evaluating, or auditing products, components, and purchased material to ensure conformance to the standards that have been imposed.
- The situation in which the probability of producing a product within specification limits is 0.9973 is referred to as Three sigma quality performance.
- Testing incoming material belong to Appraisal costs.
- Quality planning and training belongs to Prevention costs.
- Warranty adjustment belongs to External failure costs.
- Internal scrap and rework belong to Internal failure costs.
- The most effective statistical technique for reducing variability is Design of Experiments.
- Assignable cause may result on change material and/or change tool.
- Histogram requires large data, and ignores too few bins.
- A good estimator should be unbiased and has minimum Variance.

Q (2: 4pts): Two technicians perform the same drilling operation. A random sample of 12 from the first technician gives an average machining time of 3.5 minutes with variance 0.9 minutes. A random sample of 10 from the second technician yields an average machining time of 4 minutes with variance of 0.25 minutes. Use $\alpha = 0.05$, test the hypothesis that the operator's means are equal. Assume equal variances.

$$n_1 = 12$$

$$\bar{x}_1 = 3.5$$

$$s_1^2 = 0.9$$

$$n_2 = 10$$


$$\bar{x}_2 = 4$$

$$s_2^2 = 0.25$$

$$\alpha = 0.05$$

Variance are known

Acceptance Region



$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$Z_0 = \frac{(\bar{x}_1 - \bar{x}_2) - (\mu_1 - \mu_2)}{\sqrt{\frac{s_1^2}{n_1} + \frac{s_2^2}{n_2}}} = \frac{(3.5 - 4) - 0}{\sqrt{\frac{0.9}{12} + \frac{0.25}{10}}} = -1.581$$

Fail to reject H_0

$$\therefore \mu_1 - \mu_2 = 0$$

Q (3: 6 pts): The time to process purchase orders is normally distributed. A random sample of 16 orders is selected. The average processing time is found to be 9 days with a standard deviation of 2.2. Use α of 0.05


a- Can you conclude that the standard deviation is larger than 2.

$$n = 16$$

$$\bar{x} = 9$$

$$s = 2.2$$

$$\alpha = 0.05$$



$$H_0: \sigma_1^2 = \sigma_2^2 \quad H_0: \sigma_1^2 = 4$$

$$H_1: \sigma_1^2 > 4$$

$$\chi^2 = \frac{(n-1)s^2}{\sigma^2} = \frac{15(2.2)^2}{4} = 18.15$$

fail to reject H_0

$$\therefore \sigma_1^2 = 4$$

No, can't conclude.

c- Find the upper 90 % confidence interval for the mean of the order processing times.

$$P(\bar{x} + t_{\alpha, n-1} s/\sqrt{n} \geq M) = 1 - \alpha = 0.1$$

$$1 - \alpha = 0.1$$

$$\alpha = 0.1$$

$$P(9 + t_{0.1, 15} \cdot 2.2/\sqrt{16} \geq M) = 0.1$$

$$(9 + 1.341 \cdot \frac{2.2}{\sqrt{16}}) \geq M \longrightarrow (9.73755) \geq M$$

Q (4: 6 pts) A new purification unit is installed in a chemical process. Before its installation, a random sample of size = 25 yielded the following data about the percentage of impurity average of 22 and variance of 5. After installation, a random sample of size = 16 resulted in average of 16 and variance of 4. Use $\alpha = 0.05$

(a) Test the hypothesis that the two variances are equal.

$$n_1 = 25$$

$$\bar{x}_1 = 22$$

$$\sigma_1^2 = 5$$

$$n_2 = 16$$

$$\bar{x}_2 = 16$$

$$\sigma_2^2 = 4$$

$$H_0: \sigma_1^2 = \sigma_2^2$$

$$H_1: \sigma_1^2 \neq \sigma_2^2$$

$$F_0 = \frac{s_1^2}{s_2^2} = \frac{5}{4} = 1.25$$

$$F_{1-\alpha/2, n_1-1, n_2-1} = \frac{1}{F_{\alpha/2, n_2-1, n_1-1}} = \frac{1}{2.44} = 0.4098$$

Fail to reject H_0

$$\therefore \sigma_1^2 = \sigma_2^2$$

(b) Can you conclude that the both purification devices have the same mean percentages of impurity.

$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$Z_0 = \frac{(\bar{x}_1 - \bar{x}_2) - 0}{\sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}} = \frac{(22 - 16) - 0}{\sqrt{\frac{5}{25} + \frac{4}{16}}} = 8.944$$

Reject $H_0 \longrightarrow$ Purifications don't have same mean

(c) Construct the upper 90 % confidence interval on variance of old purification unit.

$$\left(\frac{(n-1)s^2}{\chi^2_{1-\alpha, n-1}} \geq \sigma_1^2 \right) = 0.1$$

$$\left(\frac{(25-1) \cdot 5}{\chi^2_{0.9, 24}} \geq \sigma_1^2 \right)$$

$$\left(\frac{24 \cdot 5}{15.66} \geq \sigma_1^2 \right) \longrightarrow (7.6628 \geq \sigma_1^2)$$

Q (5: 3 pts) A valve is produced in lots of size 36. An acceptance testing procedure consists of selecting 9 components at random from the lot without replacement and testing them. If two or more nonconforming components are found, the lot is rejected. If the lot contains four nonconforming components, calculate the desired probability using binomial approximation. Is this approximation satisfactory? Why or why not?

3

$$N = 36$$

$$n = 9$$

$$D = 4$$

$$P = D/N = 4/36 = .11$$

reject
x > 2

$$P(X \geq 2) = \sum_{x=2}^n \binom{n}{x} p^x (1-p)^{n-x}$$

$$= 1 - P(X < 2) = 1 - [P(X=0) + P(X=1)]$$

$$\Rightarrow 1 - \left[\binom{9}{0} (.11)^0 (.89)^9 + \binom{9}{1} (.11)^1 (.89)^8 \right]$$

$$= 1 - [0.350356 + 0.389723] = 0.259921$$

the approx. not satisfactory because the condition of approximation not occur

Q (6: 7 pts): The time to failure for a cathode ray tube can be modeled using a Weibull distribution with parameters $\beta = 1$ and $\theta = 300$ hours.

4 (a) What is the probability of a tube failing before 800 hours?

because $\beta = 1 \rightarrow$ so weibull convert to exponential dis

$$\lambda = \frac{1}{\theta} = \frac{1}{300}$$

$$P(X \leq 800) = 1 - e^{-\lambda x} = 1 - e^{-\frac{1}{300} \times 800} = 1 - 0.06948 = 0.930517$$

(b) What is the probability that the tube will survive 300 hours?

$$P(X > 300) = e^{-\lambda x} = e^{-\frac{1}{300} \times 300} = 0.367879$$

(c) Suppose a system is built using three identical tubes in a standby redundant system, what is the probability that the system will survive 500 hours.

\Rightarrow convert to gamma

$$P(X = 500) = \sum_{k=0}^2 \frac{e^{-\lambda x} (\lambda x)^k}{k!}$$

$$r = 3$$

$$\lambda = \frac{1}{300}$$

$$= \frac{e^{-\frac{1}{300} \times 500} \left(\frac{1}{300} \times 500 \right)^0}{0!} + \frac{e^{-\frac{1}{300} \times 500} \left(\frac{1}{300} \times 500 \right)^1}{1!} + \frac{e^{-\frac{1}{300} \times 500} \left(\frac{1}{300} \times 500 \right)^2}{2!}$$

$$= 0.18887 + 0.3148 + 0.2623 = 0.76597$$

(d) Assume the system in part c can operate with at least 2 tubes, what is the probability of system operation? (hint, use the result of part b)

$$P(r \geq 2) = 1 - P(r < 2)$$

$$1 - 0.76597 = 0.23403$$


28.5

Section: 9-10 252

4.5

1. The control chart detects assignable and chance causes. (----- False / (only assignable))
2. A product is considered defective if it contains one or more minor nonconformities. (----- True)
3. Quality is directly proportional to variability. (----- False / (inversely))
4. When six-sigma is used, the fraction nonconforming is 3.4 ppm. (----- True)
5. Length and hardness are examples of sensory quality characteristics. (----- False / (Physical))
6. Internal failure happens when a product fails to operate successfully. (----- False / (External))
7. Inspection and test of incoming material is an example of prevention costs. (----- False / (Appraisal))
8. SPC reduces variability more than design of experiment. (----- True)
9. SPC is based on sound underlying principles and can only be applied to industrial processes. (----- True)
10. Fitness for use is the modern definition of quality. (----- False / (traditional))
11. Specification limits are the parameters of the control chart. (----- True)
12. Aesthetics is "What is the reputation of the company or its products?" (----- True)
13. The Histogram is simply a frequency distribution of attribute data arranged by category. (----- True)
14. The defect concentration is a formal tool frequently useful in underlying potential causes. (----- True)
15. The scatter diagram is a useful plot for identifying a potential relationship between two variables. (----- True)
16. A process operating in the existence of assignable causes is said to be in-control. (----- False / (out of control))
17. Control charts are used to improve the process and estimating specification limits. (----- True)
18. When a process is operating properly, an out-of-control action plan should be done. (----- True)
19. SPC is effective in eliminating variability. (----- True)
20. Stem and leaf displays the three quartiles, the minimum, and the maximum of the data on a rectangular box. (----- False / (box plot))

3



Q (3): Three identical components are arranged in a standby redundant system. If the useful life of each component is described by an exponential distribution with mean failure rate of 300 hr. Please answer the followings: (10 pts)

$$\frac{1}{\lambda} = 300$$

a- Write down the density function for the useful life of the system. (2 pts)

$$\Rightarrow \lambda = 0.003$$

exponential $f(x) = \lambda e^{-\lambda x}$

b- What is the probability that a component will fail before 250 hr? (2 pts)

$$P(X \leq 250) = 1 - e^{-\lambda x} = 1 - e^{-0.003 \times 250} = 1 - 0.472 = 0.528$$


c- What is the probability that the system will survive more than 600 hrs? (3 pts)

P. to survive = 1 - P. to failure

$$P(X \leq 600) = 1 - e^{-0.003 \times 600} = 1 - 0.165 = 0.835$$

\Rightarrow prob. to survive = 0.165

d- If the useful life of the system is approximately described by a normal distribution, what is the probability that the system will survive more than 600 hrs? (3 pts)



$N(\mu, \sigma^2)$
 $N(300, 2)$

$$P(X > 600) = 1 - P(X \leq 600)$$

Standardization \Rightarrow

$$1 - \Phi\left(\frac{600 - 300}{\sqrt{2}}\right) = 1 - \Phi(212.13) \approx 1 - 0.815 = 0.185$$

Probability of survive = 0.18406

Q (4): A system consists of three modules A, B and C connected in series. The time to failure of module A follows a Weibull distribution with scale parameter $\theta = 100$ hours and $\beta = 3.2$. The time to failure of module B follows the normal distribution with mean $\mu = 400$ cycles and standard deviation $\sigma = 32$ cycles. It was also noted that during 1 hour, module B performs 12 cycles. Find the probability that the system will survive up to 240 cycles of module B. (4 pts)

per unit



Weibull | normal
 $\theta = 100$ | $\mu = 400$
 $\beta = 3.2$ | $\sigma = 32$

Q(5) The filling of glass bottles with a soft-drink beverage can be performed on two machines. The filling processes have known standard deviations of 0.03 and 0.02 liters, respectively. A random sample of 25 bottles is taken from the production of the first machine, where as a sample of 20 bottles is selected from the second machine. The averages of net weight are 2.6 and 2.8 liters, respectively. Please answer the followings: (5pts)

a- What are the quality characteristic and its type?

filling of glass (weight) \Rightarrow physical quality characteristic

b- Test the hypothesis that both machines fill the same net contents, using $\alpha = 0.05$.


2- populations \Rightarrow test on mean difference & variances known

$$H_0: \mu_1 - \mu_2 = 0$$

$$H_1: \mu_1 - \mu_2 \neq 0$$

$$\bar{z}_0 = \frac{\bar{x}_1 - \bar{x}_2 - \Delta_0}{\sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}} \Rightarrow \bar{z}_0 = \frac{2.6 - 2.8}{\sqrt{\frac{0.03^2}{25} + \frac{0.02^2}{20}}}$$

$$\Rightarrow \bar{z}_0 = \frac{-0.2}{\sqrt{0.00036 + 0.0002}} = \frac{-0.2}{\sqrt{0.00056}} = \frac{-0.2}{0.02366} = -8.45$$



5

\Rightarrow reject H_0
 \Rightarrow All same net contents

c- Calculate the P-value for the test.

$$P\text{-value} = 2[1 - \Phi(|z_0|)]$$

Q (6): Two operators perform the same machining operation. Their supervisor wants to estimate the difference in the mean machining times between them. A random sample of 10 from the first operator gives an average machining time of 4.6 minutes with a standard deviation of 0.4 minutes. A random sample of 8 from the second operator yields an average machining time of 5.4 minutes with a standard deviation of 0.5 minutes. Use $\alpha=0.05$. (10 pts)

a- Test the hypothesis that the two variances are equal. (4pts)

$$n_1 = 10$$

$$n_2 = 8$$

$$\bar{x}_1 = 4.6$$

$$\bar{x}_2 = 5.4$$

$$s_1 = 0.4$$


$$s_2 = 0.5$$

$$H_0: \sigma_1^2 = \sigma_2^2$$

$$H_1: \sigma_1^2 \neq \sigma_2^2$$

$$F_0 = \frac{s_1^2}{s_2^2} \Rightarrow \frac{0.4^2}{0.5^2} = 0.64$$


$$F_{0.025, 9, 7} = 4.82$$



$$F_{0.025, 9, 7} = 4.82$$

$$F_{0.975, 9, 7} = 0.21$$

4



Fail to reject H_0

b- If the mean machining time of the second operator should be exceed the mean of the first operator by 0.6. Can we support this hypothesis? (4 pts)

$$\mu_2 - \mu_1 = 0.6$$

$$\sigma_1^2 \neq \sigma_2^2$$

c- Find a 95% lower confidence interval for the mean machining times of the second operator. (2pts)

Q (7): The variability of the time to be admitted in a health care facility is of concern. A random sample of 15 patients shows a mean time to admission of 2.2 hours with a standard deviation of 0.2 hours. (5 pts)

a- Can we conclude that the variance of time to admission is less than 0.06 at α of 0.01? (3pts)

$n=15$ $\bar{x}=2.2$ $s=0.2$

$H_0: \sigma^2 = 0.06$

$\sigma^2 < 0.06 \Rightarrow \chi^2$

$\alpha=0.01$

$\chi^2_0 = \frac{(n-1)s^2}{\sigma^2} = \frac{14 \times 0.2^2}{0.06} = 155.55$

$\chi^2_{1-\alpha, n-1} = 4.66$

$\chi^2 = 29.14$

$\chi^2_0 = 155.55$

b- Find a 95% lower confidence interval for the mean machining times of the second operator. (2pts)

$\alpha=0.05$

$\bar{x} - t_{\alpha, n-1} \frac{s}{\sqrt{n}} \leq \mu$

$\mu \geq 2.2 - 1.761 \frac{0.2}{\sqrt{15}}$

$\mu \geq 2.1$

Q (8): Two operators perform the same machining of applying a plastic coating to Plexiglas. We want to estimate the difference in the proportion of nonconforming parts produced by the two operators. A random sample of 100 parts from the first operation shows that there are 6 nonconforming. A random sample of 200 parts from the second operator shows that 8 are nonconforming. Use $\alpha=0.01$ (5 pts)

$n_1=100 \rightarrow 6 \text{ non}$

$n_2=200 \rightarrow 8 \text{ non}$

a- Can we conclude that the difference in the proportion of nonconforming parts produced by the two operators is greater than 0.018? (2-pts)


$\hat{p} = \frac{x}{n} \Rightarrow \hat{p}_1 = \frac{6}{100} = 0.06$, $\hat{p}_2 = \frac{8}{200} = 0.04$

$H_0: \hat{p}_1 - \hat{p}_2 = 0.018$

$z_0 = \frac{\hat{p}_1 - \hat{p}_2 - 0.018}{\sqrt{\hat{p}(1-\hat{p})(\frac{1}{n_1} + \frac{1}{n_2})}} = 0.018$

$H_a: \hat{p}_1 - \hat{p}_2 > 0.018$

$\sqrt{\hat{p}(1-\hat{p})(\frac{1}{n_1} + \frac{1}{n_2})} = \sqrt{0.018 \times 0.982 (\frac{1}{100} + \frac{1}{200})} = 0.0162$



b- Test the hypothesis whether the proportion of nonconforming for second operator is equal to 4.5%.

$\hat{p}_2 = 0.045$

$\hat{p}_2 \neq 0.045$

$z_0 = \frac{(\hat{p}_2 - p_0) \sqrt{n p_0 (1-p_0)}}{\sqrt{n p_0 (1-p_0)}} = \frac{(0.04 - 0.045) \sqrt{200 \times 0.045 \times 0.955}}{\sqrt{200 \times 0.045 \times 0.955}} = -0.17$

$\sqrt{n p_0 (1-p_0)} = \sqrt{200 \times 0.045 \times 0.955} = 2.93$

c- Calculate the P-value for the test in part (b).

$P\text{-value} = 2[1 - \Phi(z_0)]$

Q (9) Consider a lot of 100 parts, of which 3 are nonconforming. A sample of 4 parts is selected, if approximation is used, what is the required probability of obtaining at most one nonconforming item? Is this approximation satisfactory? (3pts)

$N=100 \rightarrow 3 \text{ non}$

$n=4$

(hyper geometric \rightarrow binomial)

$P(X \leq 1) = P(X=0) + P(X=1)$ condition $\frac{n}{N} < 0.1 \Rightarrow 0.04 < 0.1$ \checkmark satisf

$= \binom{4}{0} (0.03)^0 (1-0.03)^4 + \binom{4}{1} (0.03)^1 (1-0.03)^3$

$= 0.88 + 0.1 = 0.99$

$B(n, p) = B(4, 0.03)$
 $P(X) = \binom{n}{x} p^x (1-p)^{n-x}$

Industrial Engineering Department
Quality Control - 96352
exam # 1

Saturday 29/3/2003
60 minutes

Name: علي محمد
Number: 0005557

Question 1: (fill in the spaces) (10 points)

1. Quality improvement is achieved through the reduction of variability in processes and products.
2. The sample average is a measure of central tendency.
3. The standard deviation is a measure of scatter, spread or variability.
4. The probability distribution of a random variable representing the number of defective units in a sample is binomial.
5. The probability distribution of a random variable representing the number of required samples until the third out of control sample point is detected is negative binomial (Pascal).
6. In acceptance sampling, the distribution of a random variable representing the number of defective units in a sample drawn from a lot of known size and percent defective is hypergeometric.
7. The probability that a point plots outside the control limits immediately after a shift in the process mean occurs is equal to $1 - \beta$.
8. The statistic that is plotted on a \bar{X} -chart is \bar{X} .
9. The R-chart is used to monitor variability within a sample.
10. The \bar{X} -chart is used to monitor variability among samples.

$$CL = \mu = \bar{x}$$

(μ) mean change $\rightarrow \bar{x}$ bar

(σ) change in standard deviation



Question 2: (true / false) (10 points)

1. $\phi(2) < 1 - \phi(-2)$ ✓ $\rightarrow \phi(2) = 1 - \phi(-2)$
2. $\phi(3) > \phi(1)$ ✓
3. $\phi(1) + \phi(-1) = 1.00$ ✓
4. Type-I error is committed when one says that the process is out of control when it is actually in control. ✗
5. Type-II error is the probability that a point plots outside the control limits. ✗
6. The relationship $\alpha = 1 - \beta$ is only true when the process is in control. ✗ (no shift, $k=0$)
7. Quality improvement is achieved through the production of products with best quality. ✗
8. The power of the chart is the probability that a point plots outside the control limits immediately after a shift in the process mean occurs. ✓ ($1 - \beta$)
9. ARL is the average number of samples required until a point plots outside the control limits by chance. ✗
10. Control charts, design of experiments and acceptance sampling are all part of the statistical methods for quality improvement. ✓

Question 3: (multiple choice questions) (10 points)

1. A cause and effect diagram is used for:
 - a. Checking randomness of data.
 - b. Checking distribution of data.
 - c. ✓ Determining reasons for possible problems.
 - d. Determining the flow of a process.
2. Which of the following statements is true?
 - a. Type-II error is the probability that a point plots inside the control limits.
 - b. The relationship $\alpha = 1 - \beta$ is always true. ✓
 - c. ✓ Type-I error is the probability that a point plots outside the control limits.
 - d. All of the above.
3. The power of the chart is:
 - a. the probability of making type-II error.
 - b. ✓ the probability that a point plots outside the control limits immediately after a shift in the process mean occurs.
 - c. the average number of samples required to detect a shift in the process mean.
 - d. The ability of a chart to detect out of control conditions.
4. A value of a measurement that corresponds to the desired value for a quality characteristic is called:
 - a. lower specification limit
 - b. ✓ nominal value
 - c. upper specification limit
 - d. process mean

5. A histogram is used for:
- Checking randomness of data.
 - ☒ Checking the distribution of data.
 - Checking trends in data.
 - None of the above.
6. Which of the following is not part of the statistical methods for quality improvement?
- control charts
 - design of experiments
 - ☒ total quality management
 - acceptance sampling
7. Which of the following a control chart does not do?
- process correction
 - process monitoring
 - ☒ detection of possible problems
 - ☒ detection of non-random process behavior
8. The performance dimension of quality answers the following question:
- what does the product do?
 - ☒ will the product do the intended job?
 - is the product made exactly as the designer intended?
 - how long does the product last?
9. The reliability dimension of quality answers the following question:
- ☒ When does the product fail?
 - How often does the product fail?
 - How long does the product last?
 - How easy is it to repair the product?
10. Which of the following statements is true?
- Quality is directly proportional to variability.
 - ☒ Quality is inversely proportional to variability.
 - Quality means fitness for use.
 - (b) and (c).

Question 4: (10 points)

- i. A production process operates with 2% nonconforming output. Every hour a sample of 10 units is taken. If 1 or more nonconforming units are found, the process is stopped. What is the probability that the process will not be stopped on the next sample?

$$P(X=0) = \binom{10}{0} (.02)^0 (.98)^{10} = (.98)^{10}$$

~~Binomial~~ $(n=10, p=0.02)$

- ii. What is the probability that at most 10% of the sample will be nonconforming?

$$P\left(\frac{X}{n} \leq .1\right) = P(X \leq 1) = P(X=0) + P(X=1) = (.98)^{10} + \binom{10}{1} (.02)^1 (.98)^9$$

$$= (.98)^{10} + 10 \cdot (.02) \cdot (.98)^9 = (.98)^9 (1 + 10 \cdot .02) = (.98)^9 (1.2)$$

Question 5: (10 points)

- i. A lot of size $N=10$ contains 3 nonconforming units. What is the probability that a sample of 3 units selected at random contains exactly one nonconforming unit?

Hypergeometric distribution

$$\frac{\binom{3}{1} \binom{7}{2}}{\binom{10}{3}}$$

$$P(1) = \frac{21}{120}$$

$$= \frac{1 \times 3 \times 21}{4 \times 2 \times 10}$$

$$6 = \sqrt{16} = 4$$

- ii. If $X \sim N(\mu, \sigma^2 = 16)$. What is the value of μ if the probability that X is less than 32 is equal to 0.5?

$$P(X < 32) = 0.5$$

$$P\left(\frac{X - \mu}{\sigma} < \frac{32 - \mu}{4}\right) = 0.5$$

$$Z = 0 \rightarrow \frac{32 - \mu}{4} = 0 \rightarrow \mu = 32$$

Question 6: (15 points)

The in-control model for a certain quality characteristic (\bar{X}) is given by $CL = 10$, $UCL = 13.09$ and $LCL = 6.91$ with 0.001 probability limits and $n = 4$.

- i. Estimate the process parameters μ and σ .

$$UCL = CL + 3.09\sigma$$

$$LCL = CL - 3.09\sigma$$

$$\mu_{\bar{X}} = CL = \mu_{process} = \bar{X} = 10$$

$$UCL = 13.09 = 10 + 3.09\sigma$$

$$\frac{13.09 - 10}{3.09} = \sigma$$

$$6\bar{X} = \frac{6\sigma_{process}}{\sqrt{n}}$$

$$6\bar{X} - 6 = 1 = \frac{6\sigma}{\sqrt{n}}$$

$$13.09 - 10 = 3.09\sigma \rightarrow 3.09 = 3.09\sigma \rightarrow \sigma = 1$$

- ii. What is the probability that a shift in mean to $\mu_{new} = 13.09$ will be detected immediately on the first sample following the shift?

$$\mu_{new} = \mu_{old} + k\sigma_{process} = 10 + k\sigma = 13.09 \rightarrow 10 + k(1) = 13.09$$

$$B = \Phi(3.09 - k\sigma) - \Phi(-3.09 - k\sigma)$$

$$B = \Phi(3.09 - 3.09\sqrt{n}) - \Phi(-3.09 - 3.09\sqrt{n})$$

$$3k = 3.09$$

$$k = 1$$

- iii. What is the average run length for this chart?

$$ARL = \frac{1}{1 - B}$$

$$1 - \Phi(0) = 0.5$$

$$B = \Phi(0) - \Phi(-6.18) = \Phi(0) = 0.5$$

Question 7: (15 points)

An \bar{X} -chart with 0.001 probability limits has been constructed to monitor a certain quality characteristic. The following two rules are used to determine if the process is out of control:

- If one sample point plots outside the control limits.
- If three consecutive sample points plot above the median.

$$Z = \frac{\bar{X} - \mu}{\sigma}$$

- i. What is α_1 associated with rule (1)? $\alpha_1 = P(X > UCL) + P(X < LCL) = P\left(\frac{\bar{X} - \mu}{\sigma} > \frac{13.09 - 10}{1} - \bar{X}\right) + P\left(\frac{\bar{X} - \mu}{\sigma} < \frac{6.91 - 10}{1} - \bar{X}\right)$

$$= P(Z > 3.09) + P(Z < -3.09)$$

$$[1 - \Phi(3.09)] + \Phi(-3.09) = 2\Phi(-3.09) = \alpha_1$$

- ii. What is α_2 associated with rule (2)?

$$Z < 0.00135 = 0.0027 = \alpha_2$$

$$\alpha_2 = (0.5)^3 = 0.125$$

- iii. Show that α -total associated with both rules is given by $1 - (1 - \alpha_1)(1 - \alpha_2)$.

Probability to $(1 - \alpha_1)$ that the point in control limit (first rule)
to $(1 - \alpha_2)$ that the point in control limit (second rule)

The probability that the process is in control is $(1 - \alpha_1)(1 - \alpha_2)$
That is in control through $1 - (1 - \alpha_1)(1 - \alpha_2)$
to be independent

Question 8: (10 points)

Consider the following data for a certain quality characteristic:

$$\Sigma \bar{X}_i = 500, \Sigma R_i = 50, m=25, n=4, d_2 = 2, d_3 = 0.9.$$

Construct appropriate \bar{X} and R charts. with 3 σ limits.

\bar{X} -chart

$$CL = M\bar{X} = \bar{\bar{X}} = \frac{\Sigma \bar{X}}{25} = \frac{500}{25} = 20 \checkmark$$

$$UCL = CL + 3\sigma_{\bar{X}} = 20 + 3\left(\frac{1}{2}\right) = 23.5$$

$$LCL = CL - 3\sigma_{\bar{X}} = 20 - 3\left(\frac{1}{2}\right) = 20 - 1.5 = 18.5$$

R-chart

$$CL = \bar{R} = M_R = \frac{\Sigma R}{25} = \frac{50}{25} = 2$$

$$UCL = CL + 3\sigma_R = 2 + 3(0.9) = 2 + 2.7 = 4.7$$


$$LCL = CL - 3\sigma_R = 2 - 3(0.9) = 2 - 2.7 = -0.7$$

= 0 (if $LCL < 0$)

\bar{X} -chart



R-chart



6 process

$$\frac{\sigma_x}{\sqrt{n}} = \frac{\sigma_x}{\sqrt{4}} = \frac{\sigma_x}{2}$$

$$\sigma_x = \frac{\sigma}{2}$$

$$\bar{\sigma} = \frac{\Sigma R}{25} = \frac{50}{25} = 2$$

$$d_2 = 2, d_3 = 0.9$$

$$\sigma_p = \sigma_x = \frac{\bar{\sigma}}{d_2} = \frac{2}{2} = 1$$

$$\sigma_x = \frac{\sigma_p}{2} = \frac{1}{2}$$

$$\sigma_R = d_3 \sigma_p = 0.9$$

$$\sigma_R = (0.9)(1) = 0.9$$

24
18
20
15
20

Industrial Engineering Department
Quality Control - 96352
exam # 1

Saturday 25/3/2000
60 minutes

Name: Rana Salah

Number: 984915


Question 1: (25 points)

I. Fill in the spaces:

1. Quality improvement is achieved through the reduction of variability in processes and products.
2. A value of a measurement corresponding to the desired value of a quality characteristic is called conformity nominal or target value.
3. The largest and smallest allowable values for a quality characteristic are called specification limits.
4. The sample average is a measure of central tendency.
5. The standard deviation is a measure of scatter spread.
6. The probability distribution of a random variable representing the number of defective units in a sample is binomial.
7. The probability distribution of a random variable representing the number of required samples until the third out of control sample point is detected is Pascal (Negative binomial).
8. The probability distribution of a random variable representing the number of defects in a square meter of carpet is Poisson distribution.
9. In acceptance sampling, the distribution of a random variable representing the number of defective units in a sample drawn from a lot of known size and percent defective is hyper geometric.
10. The relationship $\alpha=1-\beta$ is only true when process is in control actually \leftarrow no shift in mean, or standard deviation.
11. The probability that a point plots outside the control limits immediately after a shift in the process mean occurs is $1-\beta$.

II. True / False:

1. $\phi(3) = 1 - \phi(-3)$ ✓
2. $\phi(3) < \phi(2)$ X ✓
3. $\phi(3) + \phi(-3) = 0.0027$ X ✓ = 1
4. Type-II error is the probability that a point plots inside the control limits. X ✓ / process is out of control
5. The relationship $\alpha=1-\beta$ is always true. X ✓
6. Type-I error is the probability that a point plots outside the control limits. ✓
7. Quality improvement is achieved through the production of products with best quality. X ✓
8. The power of the chart is the ability of a control chart to detect out of control conditions ✓
9. ARL is the average number of samples required to detect a shift in the process mean. ✓
10. ATS is the average time until a shift in process mean is detected. ✓
11. Control charts, design of experiments and acceptance sampling are all part of the statistical methods for quality improvement. ✓
12. Control charts are designed for the purpose of process correction. X ✓
13. The performance dimension of quality answers the question "will the product do the intended job?" ✓



Question 2: (20 points)

$$P = 0.02$$

- i. A production process operates with 2% nonconforming output. Every hour a sample of 10 units is taken. If 1 or more nonconforming units are found, the process is stopped. What is the probability that the process will not be stopped on the next sample?

X : # of non conforming parts in sample (n=10) $X \sim \text{binomial}(0.02, 10)$
process not be stopped mean $P(X=0)$

$$P(X=0) = (0.98)^{10} \checkmark$$

- ii. For the same process in part (a), what is the probability that the fraction nonconforming of the next sample is less than 0.1?

$$\hat{p} = \frac{X}{n} \Rightarrow X = \hat{p}n$$

$$\hat{p} = P\left(\frac{X}{n} < 0.1\right) = P(X < 1) = P(X=0) = (0.98)^{10}$$

- iii. A lot of size $N=10$ contains 3 nonconforming units. What is the probability that a sample of 3 units selected at random contains exactly one nonconforming unit?

X : # of non conforming units in sample of size 3 $\leftarrow \text{③ } 10$


$$P(X=1) = \frac{\binom{3}{1} \binom{7}{2}}{\binom{10}{3}} = ? \quad -2$$

- iv. If $X \sim N(\mu, \sigma^2 = 16)$. What is the value of μ if the probability that X is less than 32 equals 0.5?

$$P(X < 32) = 0.5$$

$$P\left(Z < \frac{32 - \mu}{\sqrt{16}}\right) = 0.5$$

$$\frac{32 - \mu}{\sqrt{16}} = 0 \Rightarrow \boxed{\mu = 32}$$



$$\mu = 32$$

Question 3: (20 points)

The in-control model for a certain quality characteristic (\bar{x}) is given by $CL = 10$, $UCL = 13.09$ and $LCL = 6.91$ with 0.001 probability limits and $n = 4$.

Estimate the process parameters μ and σ .

$$\text{①} \mu = CL = 10$$

$$UCL = \mu + 3.09 \sigma_{\bar{x}}$$

$$13.09 = 10 + 3.09 \sigma_{\bar{x}} \quad \checkmark$$

$$3.09 = 3.09 \sigma_{\bar{x}} \Rightarrow \sigma_{\bar{x}} = 1$$

$$\sigma_x = \sqrt{n} \cdot \sigma_{\bar{x}}$$

$$\boxed{\sigma = 2} \quad \checkmark$$

$$6.91 = \mu - 3.09 \sigma_{\bar{x}}$$

$$13.09 = \mu + 3.09 \sigma_{\bar{x}}$$

$$20.00 = 2\mu$$

$$\text{①} \boxed{10 = \mu}$$

What is the probability that a shift in mean to $\mu_{\text{new}} = 13.09$ will be detected on the first sample following the shift?

$$\mu_{\text{new}} = \mu_{\text{old}} + K \sigma_p$$

$$13.09 = 10 + K(2) \Rightarrow K = 3.09/2$$

$$\beta = P(\text{Point plot in side control limit} / \text{process is out of control})$$

$$\beta = \Phi\left(\frac{3.09 - \frac{3.09}{2}(2)}{0}\right) - \Phi\left(\frac{-3.09 - \frac{3.09}{2}(2)}{0}\right)$$

$$\beta = 0.5 \quad \checkmark$$

$$P(\text{shift will be detected on first sample}) = P(\text{point is out of control limits}) = 1 - \beta = 0.5$$

0.00135
0.0027

Question 4: (15 points)

An \bar{x} control chart with 3-sigma limits has been constructed to monitor a certain quality characteristic. The following two rules are used to determine if the process is out of control:

- If two consecutive sample points plot outside the control limits.
- If three consecutive sample points plot above the center line.

i. What is α_1 associated with rule (a)?

$$\alpha_1 = P(2 \text{ points plot outside control limit} / \text{process is in control})$$

$$= P(\text{First point plot outside} / \text{in-control}) * P(\text{second point plot outside} / \text{in-control})$$

$$\alpha_1 = 2 * P(X > UCL) + P(X < LCL) = 2 * (0.0027) + (0.0027) = 0.0081$$

$$\alpha_1 = 0.0081$$

ii. What is α_2 associated with rule (b)?

$$\alpha_2 = P(3 \text{ points above center line} / \text{process is in control}) = 0.5$$

$$\alpha_2 = (0.5)^3 = 0.125$$

iii. What is overall α associated with both rules?

$$\alpha = 1 - (1 - \alpha_1)(1 - \alpha_2)$$

$$= 1 - ((1 - 0.0081)(1 - 0.125)) = 0.1178$$

Question 5: (20 points)

Thirty samples each of size 9 have been collected. $\sum \bar{x}_i = 2700$ and $\sum R_i = 120$.

Construct the in control model for both \bar{x} and R charts based on 3-sigma limits.

R-chart

$$UCL = (\sum R_i / n) + D_4 = 4 + 1.816(120/30) = 7.264$$

$$\bar{R} = CL = 120/30 = 4$$

$$LCL = (\sum R_i / n) - D_3 = 4 - 0 = 4$$

R-chart

$$UCL = 7.264$$

$$CL = 4$$

$$LCL = 0.736$$

If the R-chart was in control, estimate the process standard deviation.

$$\bar{R} = d_2 \sigma_p$$

$$4 = (2.97) \sigma_p \Rightarrow \sigma_p = 4 / 2.97 = 1.348$$

GOOD LUCK

\bar{x} -chart

$$UCL = 90 + A_2 \bar{R} = 90 + (0.337)(4) = 91.348$$

$$\bar{\bar{x}} = CL = 2700/30 = 90$$

$$LCL = 90 - (0.337)(4) = 89.652$$

$$\begin{array}{r} 1.2 \\ 0.337 \\ \hline 1.348 \end{array}$$

University of Jordan
Dept. of Industrial Engineering
Quality Control Quiz-28-12-2011)
Instructor: Dr. Abbas Al-Refaie

Name: ~~_____~~

Reg. No. ~~_____~~

Section: 11-12:30

Q.(1:10 pts) Given the following (assume normally distributed quality characteristic):

(i) The \bar{x} - R charts:

- The \bar{x} chart: CL = 625 UCL = 640 LCL = 610 $n = 9$
 - The R chart: CL = 8 UCL = 16 LCL = 0
- The specifications on the product were 620 ± 8 ,

(a) Estimate the mean and standard deviation. If the sample size is changed to three, construct the R- chart.

Mean = $\bar{\bar{x}} = CL = 625$

Standard deviation = \bar{R}/d_2 , $\bar{R} = CL = 8$ $d_{2, n=9} = 2.970$
 $= 2.6936$

$n_{old} = 9$

$UCL = D_4 \left[\frac{d_{2, new}}{d_{2, old}} \right] \bar{R}_{old} = 2.574 \left[\frac{1.693}{2.97} \right] * 8 = 11.738$

$n_{new} = 3$

$CL = \left[\frac{d_{2, new}}{d_{2, old}} \right] \bar{R}_{old} = \left[\frac{1.693}{2.97} \right] * 8 = 4.5603$

b) Calculate the process capability index.

LCL: $\left[\max \{ 0, D_3 \left(\frac{d_{2, new}}{d_{2, old}} \right) \bar{R}_{old} \right] = \frac{Zero}{2.97} \left[\frac{1.693}{2.97} \right] * 8 = Zero$

Process Capability = $\frac{USL - LSL}{6\sigma}$

$USL = 628, LSL = 612$

$\sigma = \bar{R}/d_2 = 8/2.97 = 2.6936$

$= \frac{628 - 612}{6 * 2.6936} = 0.99$

(c) What is the probability of detecting a shift in the process mean to 640 by the third subsequent sample following the shift?

Probability of detecting = $\beta^i (1 - \beta)$

$= 1^i (1 - 1)$
 $= Zero$

shift to 640
 & Mean = 640

$\beta = 1$

Kaizen Team

University of Jordan

Department of Industrial Engineering

QUALITY CONTROL (12/7/09)

DR. Al-Refai, A.

Student name:

Alaa Khailil

SR#: 20

0076322

Q(1.3) Please answer the following questions concisely:

What is the traditional definition of quality? Provide an example for each type of critical-to-quality characteristics.

Quality means fitness for use.

1) physical: weight

2) sensory: taste


3) time orientation: reliability.

What is the difference between nonconforming product and defective product?

nonconforming: that fail to meet one or more of its specifications, it is not necessarily unfit for use.

defective product: if it has one or more defect which are ~~nonconformities~~ nonconformities that are serious enough to significantly affect the safe of use (contain one or more serious nonconformities (function)).

Draw the phase diagram for the use of quality-engineering methods.



KAizen Team

Quality Control (Quiz 1)

Student Name: ~~_____~~ ID: 70707


SR#: 92

1% = The traditional definition(s) of quality is that

1. Collection of desirable Q.C.H.
2. Fitness for use.

1% = Quality costs are defined as: Categories of costs that are associated with producing, identifying, avoiding or repairing products that not meet requirements

2% = Illustrate the phase diagram of the use of quality-engineering methods:



2% = A random sample of 50 units is drawn from a production process every two hours. What is the probability that the estimated fraction nonconforming is at most 2% if the fraction nonconforming is really 0.04.

$n=50$ $p=0.04$

$P(\hat{p} \leq 0.02) = P(\hat{p} \leq 0.04)$ $\hat{p} = \frac{x}{n} \rightarrow 0.04 \leq \frac{x}{50}$

$P(X \leq 2) = P(X=0) + P(X=1) + P(X=2)$
 $\binom{50}{0} (0.04)^0 (0.96)^{50} + \binom{50}{1} (0.04)^1 (0.96)^{49} + \binom{50}{2} (0.04)^2 (0.96)^{48} = 0.364 + 0.3716 + 0.186 = 0.9214$

2% = A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the lower specification limit such that only 0.5% of the bulbs will not exceed the limit.

$P(X \leq \frac{a-\mu}{\sigma}) = 0.005$

$1 - 0.005 = 0.995$

$\frac{a-\mu}{\sigma} = -2.58$

$\frac{a-5000}{50} = -2.58 \Rightarrow a = 5129$

$LSL = \mu - 4\sigma$
 $= 10000 - 5129$
 $LSL = 4871$

2% = Surface-finish defects in a small electric appliance occur at random with a mean rate of $\lambda = 0.1$ defects per unit. Find the probability that a randomly selected unit will contain no surface-finish defects.

$P(X=0) = \frac{e^{-\lambda} \lambda^0}{0!} = \frac{e^{-0.1} (0.1)^0}{1}$

$= e^{-0.1} = 0.9048$

$P(\hat{p} \leq 0.02) = P(\hat{p} \leq 0.04)$

Kaizen Team

Quiz (1) Quality Control

Date: 16/10/2008

Name: ~~Amr~~

ID: ~~Amr~~

Q(1) What is the traditional definition of quality? Mention three quality-engineering techniques used for reducing variability.

Fitness for Use

- 1) Design of Experiments
- 2) Control Charts
- ✓ 3) acceptance Sampling

Q(2) A production process operates with % 2 nonconforming output. Every hour a sample of 20 units of product is taken, and the number of nonconforming units counted. If one or more nonconforming units are found, the sample is rejected.

$$p = 0.02$$

$$n = 20$$

1- Calculate the probability of rejecting the sample.

$$P(X \geq 1) = 1 - P(X < 1)$$

$$✓ \quad 1 - P(X=0) = 1 - \binom{20}{0} (0.02)^0 (0.98)^{20} = 0.3323$$

2- Using the poisson approximation, calculate the probability of detecting at least one nonconforming component. Is this approximation satisfactory? Why or why not?

$P < 0.1$ → the approx. is satisfactory

$$\lambda = np = 20(0.02) = 0.4$$

$$✓ \quad P(X \geq 1) = 1 - P(X < 1) = 1 - \frac{e^{-0.4} 0.4^0}{0!} = 1 - 0.67 = 0.33$$

Q(3) let x_1, x_2, x_3 , and x_4 are exponential with parameter $\lambda = 3$ and independent. If y is defined as the sum of the four distributions.

(a) What is the distribution of y ? Write the density function, $f(y)$.

y is Gamma distribution with $\lambda = 3$ & $r = 4$

$$✓ \quad f(y) = \frac{\lambda^r y^{r-1} e^{-\lambda y}}{\Gamma(r)} = \frac{3^4 y^3 e^{-3y}}{(4-1)!}$$

(b) Calculate the mean and variance for the distribution in part (a).

$$✓ \quad \text{Mean} = \frac{r}{\lambda} = \frac{4}{3} = 1.33\bar{3}$$

$$\text{Var} = \frac{r}{\lambda^2} = \frac{4}{3^2} = \frac{4}{9} = 0.44\bar{4}$$

8/10


Student Name: --- ID: --- SR#: ---

1% = The modern definition of quality is that Quality is inversely proportional to variability

1% = There are two general aspects of fitness for use:


- (1) quality of design
- (2) quality of conformance

2% = Illustrate the application of quality-engineering techniques for systematic reduction of process variability:



2% = A lightbulb has a normally distributed light output with mean 5,000 end foot-candles and standard deviation of 50 end foot-candles. Find the upper specification limit such that only 0.5 % of the bulbs will exceed the limit.

$\mu = 5000, \sigma = 50$



$P(X > USL) = 0.005 \Rightarrow P(X \leq USL) = 1 - 0.005 = 0.995$
 $P(Z \leq \frac{USL - \mu}{\sigma}) = 0.995$

$Z \leq 2.58$
 $\frac{USL - 5000}{50} = 2.58$

USL = 5129

2% = A random sample of 25 units is drawn from a production process every two hours. What is the probability that the estimated fraction nonconforming is at least 4 % if the fraction nonconforming is really 25 %. Binomial distribution

$n = 25$
 $P(\hat{p} \geq 0.04) = P\left(\frac{X}{n} \geq 0.04\right) = P\left(\frac{X}{25} \geq 0.04\right) = P(X \geq 1)$
 $= 1 - P(X \leq 0) = 1 - \left(\sum_{x=0}^0 \binom{n}{x} (0.25)^x (0.75)^{n-x}\right)$
 $= 1 - P(X=0) = 1 - P(0) = 0.99924$

2% = Surface-finish defects in a small electric appliance occur at random with a mean rate of 0.1 defects per unit. Find the probability that a randomly selected unit will contain at least one surface-finish defects.

$\lambda = 0.1$
 $P(X \geq 1) = 1 - P(X < 1) = 1 - P(0)$
 $= 1 - \frac{e^{-0.1} (0.1)^0}{0!} = 1 - 0.9048$

P(X ≥ 1) = 0.0952

UNIVERSITY OF JORDAN
 Dept. of Industrial Engineering
 Quality Control (Final Exam 4/6/09)
 INSTRUCTOR: DR. AL-REFAIE, A.

NAME: _____

ID: _____

SR. # _____

FINAL ANSWERS SHOULD BE PROVIDED WITH DETAILED CALCULATIONS

Q1.(12) Please fill in the blank the missing terms or phrases in the below table:

- ❖ The control chart detects only (1) causes. assignable
- ❖ The (2) chart is simply a frequency distribution of attribute data arranged by category. Pareto chart
- ❖ The (3) is a formal tool frequently useful in underlying potential causes. cause & effect diag.
- ❖ The (4) is a useful plot for identifying a potential relationship between two variables. scatter diag
- ❖ (5) is simply the percentage of the specification band that the process uses up. $(\bar{X}_p) \times 100\%$
- ❖ The (6) is used when the sample size n is moderately large; i.e., 10 or greater. \bar{X} -s charts
- ❖ The (7) is the number of time periods that occur until a signal is generated on the control chart. ATS
- ❖ The (8) is used when repeat measurement on the process differ only because of analysis error. Individual
- ❖ (9) is indicated when the plotted points tend to fall near or slightly outside the control limits. mixture
- ❖ The (10) is defined as the ratio of the number of nonconforming items in a population to the total number of items in that population. fraction non conforming
- ❖ If the process is out of control and capable, then the action taken to improve a process will be (11). SPC
- ❖ The (12) chart is used to control nonconformities on a product with variable inspection units. u -chart

1	assignable	7	ATS
2	Pareto chart	8	Individual - Moving range
3	cause & effect	9	mixture
4	Scatter diag.	10	fraction nonconf.
5	$\bar{X}_p \times 100\%$	11	SPC
6	\bar{X} -s chart	12	u -chart

Q2.(2) A manufacturer used the p chart with $CL = 0.1$, $UCL = 0.19$, and $LCL = 0.01$ to control a process. If the 2-sigma limits are used, find the sample size for this chart. (6-18a)

$$UCL = p + 2\sqrt{p(1-p)/n}$$

$$\Rightarrow n = p(1-p) \left(\frac{2}{UCL - p} \right)^2 \Rightarrow n = 475$$

Kaizen Team

Q3(3) In designing a fraction nonconforming chart with center line at $p = 0.2$ and two-sigma control limits.

(a) what is the sample size required to yield a positive lower control limit? (b) What is the value of n necessary to give a probability of 0.5 of detecting a shift in the process to 0.26? (6-14)

(1) $p = 0.2$ $L = 2$

$$n > \frac{(1-p) L^2}{p} \quad n > 16$$

(2) $p_m = 0.26$ $S = 0.26 \cdot 0.2 = 0.06$

$$n = \left(\frac{L}{S} \right)^2 \cdot p(1-p) = \left(\frac{2}{0.06} \right)^2 \cdot (0.2)(1-0.2) = 178$$

Q4(3) Surface-finish defects in a small electric appliance occur at random with a mean rate of 0.1 defects per unit. Find the probability that a randomly selected unit will contain at most two surface-finish defects. (2-38)

$$p(X \leq 2) = 1 - p(X > 2) = 1 - [p(X=0) + p(X=1)] = 1 - \left[\frac{e^{-0.1}}{0!} + \frac{e^{-0.1}}{1!} \right] = 0.999$$

Q5(8) Two different hardening processes A and B are used on samples of a particular alloy. Assume the hardness is normally distributed. Given that $\alpha = 0.05$ and

$(\bar{x}_A = 147, s_A = 5.0, n_A = 10)$


$(\bar{x}_B = 149, s_B = 5.5, n_B = 10)$

a(3) Test the hypothesis that the two variances are equal.

$H_0: \sigma_1^2 = \sigma_2^2$

$H_1: \sigma_1^2 \neq \sigma_2^2$

$F_0 = \frac{S_1^2}{S_2^2} = 0.826$



b(3) Test the hypothesis that the mean hardness for process A is greater than the mean hardness for process B (assume equal variances).

$H_0: \mu_1 = \mu_2$

$H_1: \mu_1 > \mu_2$

$S_p^2 = \frac{(n_1-1)S_1^2 + (n_2-1)S_2^2}{n_1+n_2-2}$

$S_p = 5.26$

$t_0 = \frac{\bar{x}_1 - \bar{x}_2}{S_p \sqrt{1/n_1 + 1/n_2}}$

$t_0 = -0.80$

c(2)- Construct a 95 % confidence on the variance of process A.

$t_{\alpha/2, n_1+n_2-2} = 1.734$

$$\frac{(n-1)S^2}{\chi^2_{\alpha/2, n-1}} \leq \sigma^2 \leq \frac{(n-1)S^2}{\chi^2_{1-\alpha/2, n-1}}$$

$$\frac{9(5^2)}{19.02} \leq \sigma^2 \leq \frac{9(5^2)}{2.7} \quad 2/4$$

$11.8297 \leq \sigma^2 \leq 83.3333$

Kaizen Team

Q6. (6) An automobile manufacturer wishes to control the number of nonconformities in a subassembly area producing manual transmissions. The inspection unit is defined as four transmissions. The following 16 samples are collected (each of size 4).

$$\begin{aligned} \bar{c} &= \bar{u} = \frac{\sum u_i / m}{n} = \frac{(\sum x_i / n)}{m} \\ &= (27/4) / 16 = 0.422 \\ UCL &= \bar{u} + 3\sqrt{\bar{u}/n} \\ LCL &= \bar{u} - 3\sqrt{\bar{u}/n} \end{aligned}$$

#	No. of nonconformities	#	No. of nonconformities
1	1	9	2
2	3	10	1
3	2	11	0
4	1	12	2
5	0	13	1
6	2	14	1
7	1	15	2
8	5	16	3

a(3)- Suppose the inspection unit is redefined as eight transmissions, design control chart for average number of nonconformities per unit.

The new sample is $n = 8/4 = 2$ inspection unit

Since this chart was established for average nonconformities per unit, the same control limits may be used.

sample size of 2 transmissions per inspection unit

b(3)- If the inspection unit is redefined as two transmissions, construct \bar{nc} -chart.

$$\begin{aligned} \bar{c} &= 27/16 = 1.6875 \\ UCL &= \bar{c} + 3\sqrt{\bar{c}} = 1.6875 + 3\sqrt{1.6875} = 3.6 \\ LCL &= \bar{c} - 3\sqrt{\bar{c}} = 1.6875 - 3\sqrt{1.6875} = 0 \\ n &= 1/2 \Rightarrow \bar{nc} = 0.84375 \\ UCL &= \bar{nc} + 3\sqrt{\bar{nc}} = 0.84375 + 3\sqrt{0.84375} = 3.6 \\ LCL &= \bar{nc} - 3\sqrt{\bar{nc}} = 0.84375 - 3\sqrt{0.84375} = 0 \end{aligned}$$

Q7. (16) Given the following (assume normally distributed quality characteristic):

(1) The \bar{x} - R charts:

- The \bar{x} chart: $UCL = 626$ $CL = 610$ $LCL = 614$

$n = 4$ specifications: 610 ± 15

- The R chart: $UCL = 18.8$ $CL = 8.2$ $LCL = 0$

(2) The \bar{x} - s charts:

- The \bar{x} chart: $UCL = 710$ $CL = 700$ $LCL = 690$

$n = 4$ specifications: 705 ± 15

- The s chart: $UCL = 18$ $CL = 8$ $LCL = 0$

1. For \bar{x} - R charts (8): (5, 50)

a(4) What would be the estimate of the fraction nonconforming and process capability index?

$$\hat{\sigma} = \bar{R}/d_2 = 8.2/2.059 \approx 4$$

$$\hat{p} = P(x < LSL) + P(x > USL)$$

$$= \Phi\left(\frac{595 - 626}{4}\right) + 1 - \Phi\left(\frac{625 - 626}{4}\right)$$

$$= \Phi(-7.75) + 1 - \Phi(-0.25) \approx 0.000129 + 0.5987 = 0.5988$$

$$\hat{C}_p = \frac{USL - LSL}{6\hat{\sigma}} = \frac{625 - 595}{6 \times 4} = 1.2553$$

