Question 17 Not yet answered Marked out of 2.50 P Flag question

Thirty samples were collected; with variable sample sizes. A control chart for the fraction nonconforming is to be established with two-sigma control limits. The sum of nonconforming was 90 and the sum of the sample sizes = 180. Using the average sample size, the UCL is -------

- 0.9082
- 1.1123

0 6

- -ocongress
  - 0.6476
- O None








Not yet answered


2.50

P Flag

question








Clear my choice

610.64



Question 1 Complete Mark 1.00 out

₹ Flag question

of 2.00

Please state whether each of the following statement is True/False. If false, please correct the false terms in the underlined text only.

- 1- <u>The x-bar and s charts are used to monitor</u> a process where automated inspection and measurement technology is used.
- 2- <u>There is a mathematical or statistical relationship</u> between the control limits and the specification limits.
- 1- False, The x-bar and s charts are used to monitor --> The Shewhart control chart
- 2- False, There is a mathematical or statistical relationship There is no mathematical or statistical relationship





Question O	Please state whether each of the following statement is True/False. If false, please correct the false terms
Complete	in the underlined text only.
Mark 0.00 out of 2.00	1- A point plots outsides both the limits of the individual and moving range charts indicates that the
₹ Flag	variability of the process is out of control.

2- Stratification pattern is indicated when the points in the control chart cluster around the center line.

Question 11	The x-bar and s chart was used to monitor process. Twenty samples were collected each of sample size = 9. The standard values of the mean and standard deviation are 112 and 2, respectively. Specification on the critical characteristic is USL= 118, target=111, LSL= 106. Then, the appropriate capability index will be		
Not yet answered			
Marked out of 2.50			
P Flag question	○ Cpkm     ○		
	O Cp		
	ОСР		
	O Cpm		
	Clear my choice		


Question 4
Complete
Mark 1.00 out
of 2.00

question

Please state whether each of the following statement is True/False. If false, please correct the false terms in the underlined text only.

1-Specification limits are calculated, for example by customers or designers.

2- When constructing the x-bar and R control charts, if the cost associated with <u>producing defective</u> <u>items is high, large, more frequent samples</u> are recommended.



The x-bar and R control charts are used to monitor the thickness of plastic bottle. Twenty five sample were collected each of sample size =4. Given the following: sum of sample averages= 1000 Sum of sample ranges = 20 a- estimated process mean

Question 13 Not yet answered Marked out of 2.50 P Flag question

A control chart for the fraction nonconforming is to be established by selecting twenty samples each with sample size of 40 units. The sum of nonconforming units = 96. Suppose that two points fell outside the control limits. The corresponding number of nonconforming was 2 and 4, respectively. Then the revised CL will be ------

- 0.0474
- 0.125
- 0.1184
- 0.133333
- O None

Question 1 Not yet

Marked out of

answered

P Flag question

2.50

The x-bar and s chart was used to monitor a new process. The standard values of the mean and standard deviation are 100 and 3, respectively. Specification on the critical characteristic is at most 118. Then, the minimum recommended capability value is ----.

- O None
- 0.5
- •
- 0
- 0 6

Question 1 Not yet

Marked out of

answered

P Flag question

2.50

The x-bar and s chart was used to monitor a new process. The standard values of the mean and standard deviation are 100 and 3, respectively. Specification on the critical characteristic is at most 118. Then, the minimum recommended capability value is ----.

- O None
- 0.5
- •
- 0
- 0 6

Question 2

Complete

Mark 3.00 out of 4.00

P Flag question The x-bar and R control charts are used to monitor the thickness of plastic bottle; specifications are at most 95.

Twenty sample were collected each of sample size =4. Given the following (standard values **are unknown**):

X-bar chart: CL= 100 UCL= 103

Calculate:

a- CL of the R chart


b- If the process mean shifts to 102 and the standard deviation becomes 4. Calculate the probability to detect the shift by the third sample.

c- out-of-control Average Run Length assuming the shift is detected by the 1st sample.





Question 4	The x-bar and S charts (standard values are known) are used to monitor weight (Specifications 100±9).			
Not yet answered	Twenty samples were collected (n =4), Given:			
Marked out of	x-bar: CL = 101			
2.50	s chart: CL = 9			
P Flag question	The values of process standard deviation and mean are			
	o mean= 100, standard deviation = 9.788			
	O None			
	O mean= 101, standard deviation = 8.2917			
	• mean= 101, standard deviation = 9.788			
	O mean= 100, standard deviation = 9			
	Clear my choice			



Question 5 The x-bar and s control charts are used to monitor the thickness of plastic bottle; specifications are at Not answered most 95. Marked out of Twenty sample were collected each of sample size =9. Given the following (standard values are known): 6.00 X-bar chart: CL= 100 P Flag question s chart: CL= 9 Calculate: a- alpha risk b- UCL of s chart c- Fraction nonconforming d- UCL of the corresponding s chart

