

# Drilling Machine...

Click to add text

# Drilling

- Drilling is the operation of producing circular hole in the work-piece by using a rotating cutter called **DRILL**.
- The machine used for drilling is called drilling machine.
- The drilling operation can also be accomplished in lathe in which the drill is held in tailstock and the work is held by the chuck.
- The most common drill used is the **twist drill**.

# Drilling Machine

It is the simplest and accurate machine used in production shop.

The work piece is held stationary ie. Clamped in position and the drill rotates to make a hole.

Types :-

a) Based on construction:

Portable, Sensitive, Radial, up-right, Gang,  
Multi-spindle

b) Based on Feed:

Hand and Power driven

# Sensitive Drilling Machine

- Drill holes from 1.5 to 15mm
- Operator senses the cutting action so sensitive drilling machine





Fig.


## Up-Right Drilling Machine




- Drill holes upto 50mm
- Table can move vertically and radially

# Radial Drilling Machine

- It is the largest and most versatile used for drilling medium to large and heavy work pieces.





# Drill Materials

The two most common types are

1. HSS drill

- Low cost

2. Carbide- tipped drills

- high production and in CNC machines

Other types are

Solid Carbide drill, TiN coated drills, carbide coated masonry drills, parabolic drills, split point drill



# Drilling And Drills

## Types of drills

- Twist drill: most common drill
- Step drill: produces holes of two or more different diameters
- Core drill: used to make an existing hole bigger

(a) Twist drill



(c) Straight-flute drill



(b) Step drill




(d) Spade drill



(e) Gun drill




(f) Drill with brazed carbide tip



(g) Drill with indexable carbide inserts




# Drill fixed to the spindle



## Drilling operations

- Drilling Centre Hole
- Drilling Deep Holes
- Drilling Thin Material
- Drilling Pilot Hole



# Tool Nomenclature



# Tool Holding devices


- The different methods used for holding drill in a drill spindle are
  - By directly fitting in the spindle hole.
  - By using drill sleeve
  - By using drill socket
  - By using drill chuck

# Work Holding Devices




(c) Drill socket

Drill holding devices



Safety Drill Drift




# Drilling operations...


- Operations that can be performed in a drilling machine are

- Drilling
- Reaming
- Boring
- Counter boring
- Countersinking
- Tapping


# Operations in drilling machine




Counter Boring




Drilling




Tapping



Boring




Reaming



Countersinking

# Operations in drilling machine





## Types of cutters

### Reamers :-

Multi tooth cutting tool

Accurate way of sizing and finishing the pre-existing hole.

Accuracy of  $\pm 0.005\text{mm}$  can be achieved

### Boring Tool:-

Single point cutting tool.

Boring tool is held in the boring bar which has the shank.

Accuracy of  $\pm 0.005\text{mm}$  can be achieved.

## Countersinks :- Types of cutters

Special angled cone shaped enlargement at the end of the hole

Cutting edges at the end of conical surface.


Cone angles of  $60^\circ$ ,  $82^\circ$ ,  $90^\circ$ ,  $100^\circ$ ,  $110^\circ$ ,  $120^\circ$

## Counter Bore Tool:-


Special cutters uses a pilot to guide the cutting action .

Accommodates the heads of bolts.

# Counter bore and spot facing



a




b


Countersunk hole

Not good  
because it rip  
clothes

Not good, collect  
dust



Counterbored hole



Spot faced hole

# Types of cutters

## Combined Countersinks and central drill :-

Special drilling tool to start the hole accurately.  
At the end it makes countersinks in the work piece.

## Gun drill :-

Machining of lengthy holes with less feed rates.  
To overcome the heating and short life of the normal drill tool

# Types of cutters


## Tapping:-

For cutting internal thread

Multi cutting edge tool.


Tapping is performed either by hand or by machine.

Minor dia of the thread is drilled and then tapping is done.



# Work Holding Devices

- 1. Machine Table Vice




Standard machine table vice

Swivel vice

# Work Holding Devices

- Step Blocks
- Clamps
- V-Blocks
- Angles
- Jigs
- T- Slots Bolt



# Definitions

- Cutting Speed (v):-

It's the peripheral speed of the drill

$$v = \pi * D * N \text{ where}$$

D = dia of the drill in m

N = Speed of rotation in rpm

Feed Rate (f):-

It's the movement of drill along the axis (rpm)

Depth of Cut (d):-

The distance from the machined surface to the drill axis

$$d = D / 2$$



## Material Removal Rate:-

It's the volume of material removed by the drill per unit time

$$\text{MRR} = (\pi D^2 / 4) * f * N \text{ mm}^3 / \text{min}$$

## Machining Time (T) :-

It depends upon the length (L) of the hole to be drilled , to the Speed (N) and feed (f) of the drill

$$t = L / f N \text{ min}$$

# Precautions for Drilling machine

- Lubrication is important to remove heat and friction.
- Machines should be cleaned after use
- Chips should be removed using brush.
- T-slots, grooves, spindles sleeves, belts, pulley should be cleaned.
- Machines should be lightly oiled to prevent from rusting

# Safety Precautions

- Do not support the work piece by hand – use work holding device.
- Use brush to clean the chip
- No adjustments while the machine is operating
- Ensure for the cutting tools running straight before starting the operation.
- Never place tools on the drilling table
- Avoid loose clothing and protect the eyes.
- Ease the feed if drill breaks inside the work piece.