1. The significance of a test is:

- the identification of the properties of materials through well-established procedures
- in its ability to predict the performance of a materials in service
- c) the supplement of the classroom instructions in Materials Science and Engineering through demonstration of basic principles of material properties
- d) to introduce the student to the safety signs in order to avoid any undesired circumstances

2. The name of the figure and table are written:

- a) Above the figure and below the table
- b) Above the figure and above the table
- below the figure and below the table
- d) below the figure and above the table

3. If the experimental uncertainty is presented as shown in equation $R = 90.1 \pm 0.1$ (20:1), then (20:1) indicates that:

- a) 19 out of every 20 measurements are expected to be equal to or between the value 90.0 and 90.2
- b) 19 out of every 20 measurements are expected to be equal to 90.0
- 19 out of every 20 measurements are expected to be equal to the value 90.1
- d). 19 out of every 20 measurements are expected to be equal to or between the value 90.1 and 90.2

4. The degree of segregation is determined by:

- a) Microetching
- b) Carbunizing
- v) Macroetching
- d) Mochanical testing.

5. It is recommended to use silicon carbide wheels to cut:

- a) Ferrous alloys
- b) Ceramic materials
- s) non-ferrous alloys
- d) Sensored carbide materials

6. In most cases the surface roughness of the specimen can be removed almost totally by:


- a) Custing, growling and polishing
- b) Cutting and grinding only
- v) Grunding only
- d) Grinding and polishing

7. Etching may be done by:

- a) immersing the specimen face up in a shallow beaker of the reagent
- b) awabbing the face of the specimen with cotton c) leaving the specimen in a shallow heaker of the reagent for at least one hour

8. Case depth for carbon penetration can be obtained for carburizing, using the following simple formula:

- a) Case depth= x = v(2Dt), Where: D-diffusion coefficient (cm/s), t-time of diffusion (s)
- b) Case depth= x = 2D v(t), Where: D- diffusion coefficient (cm /s), t- time of diffusion (s)
- c) Case depth= x = 2v(Dt), Where: D-diffusion coefficient (cm2s), t-time of diffusion (s)
- d) Case depth= x = ty(2D), Where: D- diffusion coefficient (cm2 x), t- time of diffusion (s)



- a) Brinell
- b) Knoop
- c) Vickers
- d) Rockwell

10. The following tests are not used for microhardness testing:

- a) Brinell only
- b) Knoop only
- c) Vickers only
- d) Band C

11. The Brinell hardness number usually falls within a range of:

- w) 75 to 300
- b) 90 to 630
- 240 to 3000

d) 250 to 450

12. The method that you used to construct the phase diagram in the lab is:

- a). The mechanical properties rectinique
- b) The thermal analysis technique
- The casting technique
- The grain size calculation sectorings

13. The magnetic particle method of inspections is a procedure used to:

- a) determine the presence of defects at or near the surface of ferromagnetic objects
- b) determine the presence of defects at the surface of ferromagnetic objects only
- c) determine the presence of defects near the surface of non ferromagnetic objects
- d) determine the presence of defects at or near the surface of ceramic objects

14.eddy current testing is the most wildly used non-destructive testing technique:

- a) in the non-ferrous wrought metal industries.
- b) the ferrous wrought metal industries
- c) for the detection of surface and near surface defects in products of uniform section such as but tubes and wire
- d) a and c

Transmitting and receiving transducers are used at the cases time for the following nondestructive testing method:

- A) Yeardington market
- We Water Harden State of Party Line
- el Die promise medical

Defects are revealed, in the radiographic sessing, through

- by worth the sex selection to the companies sold to be the low the total transmirtale report and the record of the reference when form the table with of the company
- The indication of the parameter's prices and referring whereast means, and the recommend of the test

17. When calculating the case depth for the carbarized specimen, the formula In question 8 is used. This means that:

- the temperature is not a factor
- Mr. The temperature is implicitly estimated to the
- Of the improves in implicate textuded in the
- If a part is included in a said arrother part is included in the

18. In Sulphur printing, the paper will darken due to formation of: NY PROP

O ALL

b) The following photo macrograph (Figure 1) shows:

- to manufacture of populate in a wealt can input of summerceally year distriction.
- By Internal oracks of his forgod NG-2018
- 63. Place limits of Frequel mentions of alamanan 2018 specimen
- By Canno stations through a contract and box with a case South of Conn.



Flance:1

e) The grinding direction of successive steps are those shown in: c) Figure 4 by Physics ? Franco J Figure 5 Frgurs A Pigner)

1.) a zest 3.) a 4.) 5.) 6.)0 7) d 8.) a 9.)1 10.)a 11.) 5 12.) 6 13.)a 14.)] 15)9 16./ 17 18.) 6 c] the

28-1 pe = 1